

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21006942/R1tf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924		[Date:	05/11/2021	
			(Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SDL 6581P	Veh. Inspected		SMZ 7962L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010620/HA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		23/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FREED HYBRID 1.5G A	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GB73141326	Colour		BLUE	
	Odometer	2962 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/65 R15	DUNLOP		6 mm	
	L/H Front Tyre	185/65 R15	DUNLOP		6 mm	
	R/H Rear Tyre	185/65 R15	DUNLOP		6 mm	
	L/H Rear Tyre	185/65 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/06/2021	Inspection Date	!	29/06/2021	
	Survey held at	Survey held at 56 LOYANG WAY #04-04				
	Repairer	rer AP AUTOMOTIVE SERVICES PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: