

- Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details**
 - Vehicle & Driver Details
 - Vehicle Condition
 - Taxes & Ratio
 - Parts & Labour
 - Miscellaneous
- Summary

General Details

Involving	TPVD BMW 428I (SDS8886K)
Date of Loss	20 June 2021
Time of Loss	11:00
Loss Description	SKK80E (INSD) HIT PARKED SDS8886K (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	-\$66,725.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>

-  Service Requests
-  Messages
-  Claims

Assessment Details

- General & Workshop Details
 - Vehicle & Driver Details**
 - Vehicle Condition
 - Taxes & Ratio
 - Parts & Labour
 - Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#	SDS8886K	Purchase Date	<input type="text" value="DD/MM/YYYY"/> 
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="30/10/2015"/> 
Mileage	<input type="text" value="19674"/>	Age of Vehicle	5

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2014"/>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	GEORGES SIMON SALO	<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD BMW	B.M.W.
Model	428I	428I GRAN COUPE A/T
Type		<input type="text" value="v"/>
Type of Paint		<input type="text"/>
Chassis No		WBA4A52020GA69269
Engine No		B2830955N20B20A
Engine Capacity		1997
Sum Insured		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	4 November 1960	DD/MM/YYYY 
Age	60	
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="v"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text" value="v"/>
License Issue Date		DD/MM/YYYY 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY 
Address	Singapore	
Address type	Personal Correspondence	
Gender	Unknown	
Marital status	Unknown	
Identification #	SXXXXX322G	

Assessment Details

- General & Workshop Details
 - Vehicle & Driver Details
 - Vehicle Condition**
 - Taxes & Ratio
 - Parts & Labour
 - Miscellaneous
- Summary

Detailed Assessment

Inspection Date * 

Total Loss

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/ Unnamed Driver Excess

Condition of Vehicle at time of survey

General condition 

Steering (Serviceable)

Footbrake (Serviceable)

Handbrake (Serviceable)

Engine Modification

Pre-accident condition 

Other Excess

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

- Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio**
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="5"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<input type="button" value="Yes"/> <input checked="" type="button" value="No"/>
Paint Material Ratio	<input type="text" value="80"/>	Part Supplied by AXA	<input type="button" value="Yes"/> <input type="button" value="No"/>

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour**
- Miscellaneous
- Summary

Parts

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P/
	0	1		REAR RIGHT DOOR	Bent	0	1369.6	No	0	5	0	0	1301.12	Re
	0	10		REAR RIGHT DOOR PANEL CLIP	Necessary	0	7.49	No	0	5	0	0	71.16	Re
	0	1		REAR RIGHT WINDOW GEAR REGULATOR	Repair	0	0	No	0	0	0	0	0	De

Labour

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		LABOUR TO REMOVE DAMAGED DOOR & TO INSTALL NEW DOOR	0	60	0	0	Reviewing		

VendorEngage

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		LABOUR TO REMOVE DAMAGED DOOR MECHANISM, WINDOW GLASS, DOOR WEATHER STRIPE, RUN CHANNEL, DOOR LOCK, DOOR KNOB, DOOR HANDLE ONTO NEW DOOR & RESETTING POWER WINDOW	0	250	0	0	Reviewing		
	0		LABOUR TO KNOCK FRONT RIGHT DOOR & CENTER PILLAR	0	0	0	0	Deny		
	0		PAINT SPRAYING REAR RIGHT DOOR INSIDE & OUTSIDE & FRONT RIGHT DOOR	0	600	0	0	Reviewing		
	0		TO CHECK REAR RIGHT DOOR ELECTRICAL & MECHANISM FUNCTIONALITY	0	30	0	0	Reviewing		

-  Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous**

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 4 DAYS	Reviewing	0	0		

- Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,312.28
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$1,372.28
Labour	\$0.00	\$940.00

Submit for Review