

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA & TOKIO	DATE	: 17/06/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMC4112P		
MODEL	: TOYOTA CHR HYBRID		
CHASSIS NO			
<u>ACCIDENT DETAILS</u> DATE : 16/06/2021			
TIME : 19:23HRS			
THIRD PARTY REQUESTOR / CONTACT : JACK			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Repl</i>	1	\$ 1,366.90	\$ 1,366.90
2	BOOTLID DETECTOR <i>ould</i>	1	\$ 280.30	\$ 280.30
3	BOOTLID WINDSCREEN MOULDING <i>new</i>	1	\$ 211.30	\$ 211.30
4	REAR BUMPER <i>Repl</i>	1	\$ 850.00	\$ 850.00
5	REAR BUMPER LOWER LID <i>Repl</i>	1	\$ 420.00	\$ 420.00
6	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
7	REAR BUMPER REINFORCEMENT <i>Repl</i>	1	\$ 555.00	\$ 555.00
8	REAR BUMPER TOWING COVER <i>Repl</i>	1	\$ 66.50	\$ 66.50
9	REAR BUMPER BRAKELIGHT HOUSING <i>ould</i>	1	\$ 90.00	\$ 90.00
10	REAR END PANEL <i>Repl</i>	1	\$ 680.00	\$ 680.00
11	REAR END PANEL TOP GARNISH <i>Repl</i>	1	\$ 230.50	\$ 230.50

TOTAL PRICE \$ 4,875.30

LESS 25% \$ 1,218.83

SUB TOTAL PRICE \$ 3,656.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00

2	BOOTLID WINDSCREEN SEALANT <i>None</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
3	REAR BUMPER CLIP(SET) <i>None</i>	1	\$ 20.00	\$ 20.00	<i>/</i>
4	REAR END PANEL SEALANT <i>None</i>	1	\$ 60.00	\$ 60.00	<i>/</i>
5	REAR END PANEL TOP GARNISH CLIPS(SET) <i>None</i>	1	\$ 20.00	\$ 20.00	<i>/</i>
6	REVERSE SENSOR <i>Damaged</i>	1	\$ 200.00	\$ 200.00	<i>/</i>

300

TOTAL \$ 410.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING REMOVAL AND REPLACING PARTS	\$ 1,200.00	<i>500</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>600</i>	
3	TUFF COAT	\$ 60.00	<i>40</i>	
4	WIRING CHECK	\$ 30.00	<i>✓</i>	
5	UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 60.00	<i>40</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 50.00	<i>✓</i>	
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 50.00	<i>x</i>	
8	TRANSFER BOOT LID MECHANISM	\$ 60.00	<i>x</i>	
9	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>x</i>	

1260

TOTAL

\$ 2,830.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 4 066.48
TOTAL LABOUR COST \$ 2 830.00
TOTAL REPAIR COST \$ 6 896.48

APPROVED DETAILS

EXCESS

NO. OF DAYS

RE-SURVEY

PART BY PART OR LUMP SUM \$ 5350

DATE & TIME OF SURVEY

SURVEYED BY Ikk-adrian

CONTACT NUMBER 9689 3735

FAX NUMBER

Adrian Ly

r/s 18/06/21.

05 Days

total 3768.22

L/S 3K