



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21006953/Aga3q2 Date: 09/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 4468H	Veh. Inspected	SNA 8383X
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03CBL	Excess (\$)	0.00
	Assign From		Assign Date	23/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053AK5004011331	Colour	BLACK
	Odometer	74457 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	MICHELIN	6 mm
	L/H Front Tyre	215/55 R17	MICHELIN	6 mm
	R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
	L/H Rear Tyre	215/55 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/06/2021	Inspection Date	23/06/2021
	Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	