

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21006962/APA3Q2
Date: 11/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKS209K	Insured Vehicle No :	SMQ1942G
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	8725295955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS209K	Engine No:	CZDC15328
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Chassis No:	WAUZZZF38M1041380
Reg. Date:	30/12/2020 (Man. Year: 2020)	Odometer:	8110 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,842.00	1,224.80	3,617.20	74.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,002.00	2,550.00	56.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,394.00	3,226.80	6,167.20	65.65
+ GST 7.00/7.00% (S\$)	657.58	225.88	431.70	65.65

Nett Amount (S\$)	10,051.58	3,452.68	6,598.90	65.65
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,752.68		

INSPECTION

Date of Assignment: 23/06/2021

Date Inspected: 23/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,634.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Distorted	459.00 FS	*367.20 FS
3	1		*REAR BUMPER GRILLE -LH	Not Necessary	152.00 FS	*- FS
4	1		*REAR ULTRASOUND SENSOR BRACKET -LH	Not Necessary	25.00 FS	*- FS
5	1		*REAR BUMPER CROSS REINFORCEMENT -CENTER	Not Necessary	97.00 FS	*- FS
6	1		*REAR BUMPER BRACKET -CENTER	Not Necessary	48.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR -LH	Not Necessary	41.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	651.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	58.00 FS	*- FS
10	1		*REAR BUMPER SHOCK ABSORBER	Not Necessary	85.00 FS	*- FS
11	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
13	2		*REAR WHEEL COVER -LH/RH	Necessary	1,072.00 FS	*857.60 FS
14	1		*PACKING ADHESIVE	Not Necessary	19.00 FS	*- FS
15	1		*AUDI EMBLEM	Not Necessary	138.00 FS	*- FS
16	1		*Q3 EMBLEM	Not Necessary	99.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**4,842.00****1,224.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER ,REAR LID AND BOTH REAR WHEEL ARCH TRIMS	New	2,800.00	950.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,552.00	2,002.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >