



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SDF7171P

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 50618
Reg No/Reg Date SDF7171P / 10/09/2015
Date In/Mileage / 0
Chassis No WDD2221652A201565
Engine No 27682430232900
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian Bl/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	23/06/2021/ 12:08	CH	371 / Go Chee Han
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

- 7 REQUEST
Customer Request
M-BPNSUN
POLICY NO/ACC DATE : 2100428127-04 // 21-6-2021
DRIVE IN/TP VEH NUMBER : 22-3-2021 // SDP2353P - FIRST CAPITAL
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:
A BPILAB
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.
A BPIRES
RESpray REAR BUMPER
A BPILAB
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT
A BPILAB
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT
M REAR BUMPER de-
M LOWER PART TRIM BUMPER ? XSV
M FOG TAIL LAMP ? XSV
M LEFT ORNAMENTAL TRIM de-
M RIGHT ORNAMENTAL TRIM de-

960 1920.00

600 780.00

480.00

120.00

1.00 2204.73 00.00 2204.73

1.00 518.33 00.00 518.33

1.00 281.75 00.00 281.75

1.00 117.30 00.00 117.30

1.00 117.30 00.00 117.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirmed & accepted by

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Rasul
4p 90010068
3 days
22/07/21 @ 1100
Resy before paint

7% GST on Net 6,539.41
6539.41 457.76

Total Payable 6,997.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - a registered trademark of Daimler AG, Stuttgart, Germany

Page 1 of 1



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDF7171P

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **50618**
Reg No/Reg Date **SDF7171P / 10/09/2015**
Date In/Mileage **22/07/2021 / 66167**
Chassis No **WDD2221652A201565**
Engine No **27682430232900**
Make/Model **MB/S 400 L BlueEFFICIENCY SE**
Colour/Trim **021 197 Obsidian Bl/ 048 805 Orient Beig**

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	13/08/2021/ 18:53	CH	371 / Go Chee Han			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE : 2100428127-04 / 21-6-2021
DRIVE IN/TP VEH NUMBER : 22-3-2021 // SDP2353P - FIRST CAPITAL
DATE IN/DATE SURVEY: 22-7-2021 // RASUL - LKK
DIRECT SETTLEMENT BY: 19-7-2021 // RACHEL WU - FIRST CAPITAL
X REAR RIGHT MOUNTING RAIL **cra**

1.00 87.46 00.00 87.46

ESTIMATE

Confirmed & accepted by

Nett 87.46
7% GST on 87.46 6.12
Total Payable 93.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany