

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Jun-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6951 E

1 pc	Rear bumper	\$	696.00	CRK
1 pc	Rear bumper lower cover	\$	206.00	DEF
		\$	902.00	
		\$	90.20	
	Less 10%	\$	811.80	
S/NETT				
1 set	Rear bumper clips	\$	48.00	NEL
	Sundry	\$	50.00	XNN
	Towing Fee	\$	50.00	? need receipt
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	120.00 / 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	XNN
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	550.00	180
	To putty and spray painting on rear bumper	\$	250.00	180
		\$	2,059.80	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 CLK
24/6/2021 1710
L/S
2 DAY
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: