

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

C10010619/HA

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

153.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

LTA 33418

Vehicle: IN / OUT

Veh No:

SKV3127C

Yr Regn:

10/9/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make:

Nissan Qashqai

c.c

1197

Colour:

Red

K.C.

Insured / Std / NI / NA

Sp. Reading

65824

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEAJ1141442879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/6/14

D.O.I.

30/6/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/3/14 No Second hand parts. 2x100c.
owner went replace new bumper
P1P 1746.83 confirmed with Mr Tan (Red \$5697.63, 77%)

Date/Time, File Pass to?

☐

Preli. Report

1) 05/07 Typist

☐

Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$) 1746.83

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$ SI

) Photos

) Others

TOTAL

Budget Direct Insured's Veh No : SLC5876Z

Date of Accident : 22 June 2021


TAN LIM MOTOR PTE LTD
 1 Defu Lane 6 Singapore 539365
 Tel: 68585151 (24 Hours) Fax: 68580877
 GST Regn. No. : M2-8922054-2
 Acknowledged by Repairer
 Signature: _____
 Date: _____ Date : 23 June 2021

Mr Tan Ee Beng

p/p \$ 1746.83

not Authorized
 22/6/21
 30/6/21
 2 days
 4/5

Estimate To Repair SKV3127C - NISSAN QASHQAI 1.2 DIG-T CVT
 Chassis No : SJNFEAJ11U1442879

S/No	Quantity	Description	Amount	
NETT ITEMS				
01	1 pc	tailgate lid	\$ 2,656.90	X
02	1 pc	tailgate lid lock top	\$ 162.20	X
03	1 pc	tailgate lid lock striker	\$ 50.30	X
04	1 pc	tailgate lid weatherstrip	\$ 190.60	X
05	1 pc	tailgate lid centre logo badge	\$ 64.60	X
06	1 pc	tailgate lid Qashqai badge	\$ 64.60	X
07	1 pc	rear bumper	\$ 831.00	X
08	2 ps	rear bumper bracket @ \$91.70	\$ 183.40	X
09	2 ps	rear bumper side retainer @ \$55.10	\$ 110.20	X
10	1 pc	rear bumper centre cover c/w bumper	\$ 219.40	X
11	1 pc	rear bumper absorber foam	\$ 133.80	X
12	1 pc	rear end panel	\$ 540.90	X
13	2 ps	rear bumper reflector @ \$57.00	\$ 114.00	X
14	3 ps	rear bumper upper clip holder @ \$12.10	\$ 36.30	X
15	2 ps	rear bumper end splashield cover @ \$45.60	\$ 91.20	X
Less 10 %			\$ 5,449.40	
			\$ 544.94	
			\$ 4,904.46	
SPECIAL NETT ITEMS				
16	1 pc	rear windscreen glass sealant	\$ 20.00	X
17	1 pc	rear windscreen inner sponge seal	\$ 20.00	X
18	1 set	rear bumper parking sensor	\$ 350.00	200
			\$ 390.00	
LABOUR & MISC. CHARGES				
01		To check electrical lighting concerned.	\$ 60.00	20
02		To rust-proofing of the affected areas.	\$ 150.00	X
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00	X
04		To reinstall of rear bumper parking sensor.	\$ 80.00	40
05		To remove and refit rear windscreen glass.	\$ 140.00	X
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00	250
07		Putty and spray painting of the affected portion.	\$ 800.00	500
			\$ 2,150.00	
Total			\$ 7,444.46	

p-818.70
 102
 736.83
 1746.83