



TAN LIM MOTOR PTE LTD

Budget Direct Insured's Veh No : SLC5876Z

Date of Accident : 22 June 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Tan Ee Beng

Date : 23 June 2021

Estimate To Repair SKV3127C - NISSAN QASHQAI 1.2 DIG-T CVT

Chassis No : SJNFEAJ11U1442879

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	tailgate lid	\$ 2,656.90
02	1 pc	tailgate lid lock top	\$ 162.20
03	1 pc	tailgate lid lock striker	\$ 50.30
04	1 pc	tailgate lid weatherstrip	\$ 190.60
05	1 pc	tailgate lid centre logo badge	\$ 64.60
06	1 pc	tailgate lid Qashqai badge	\$ 64.60
07	1 pc	rear bumper	\$ 831.00
08	2 ps	rear bumper bracket @ \$91.70	\$ 183.40
09	2 ps	rear bumper side retainer @ \$55.10	\$ 110.20
10	1 pc	rear bumper centre cover	\$ 219.40
11	1 pc	rear bumper absorber foam	\$ 133.80
12	1 pc	rear end panel	\$ 540.90
13	2 ps	rear bumper reflector @ \$57.00	\$ 114.00
14	3 ps	rear bumper upper clip holder @ \$12.10	\$ 36.30
15	2 ps	rear bumper end splashshield cover @ \$45.60	\$ 91.20
			\$ 5,449.40
		Less 10 %	\$ 544.94
			\$ 4,904.46
		<u>SPECIAL NETT ITEMS</u>	
16	1 pc	rear windscreen glass sealant	\$ 20.00
17	1 pc	rear windscreen inner sponge seal	\$ 20.00
18	1 set	rear bumper parking sensor	\$ 350.00
			\$ 390.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00
04		To reinstall of rear bumper parking sensor.	\$ 80.00
05		To remove and refit rear windscreen glass.	\$ 140.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
07		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 2,150.00
		Total	\$ 7,444.46