

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0499/2021/ZK  
**DATE** : 18-Jun-21  
**WIP** : 31921

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/2021**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**9 days exclude 2 Sundays & 1 PH**

**Johnny Boo 24 Aug 21**

**OWNER'S NAME** : MS AMELIA SANTOSA  
**ADDRESS** : 15 EVELYN ROAD  
SINGAPORE 309311  
**TELEPHONE** : HP +65 90177169  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1800149049-02  
**VEHICLE NO** : **SJE 3277 D**  
**MODEL CODE** : A4 SEDAN 2.0 TFSI S TRONIC  
**MODEL YEAR** : 24/12/2018  
**ENGINE NO** : CVK 072177  
**CHASSIS NO** : WAUZZZF48KN000861  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Jun-21  
**PLACE OF ACCIDENT** : RESIDENCES @ EVELYN CONDOMINIUM

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 3277 D**

| S/N                             | NATURE OF JOBS                                                                                                                                                                 |          | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------------------------|
| 1                               | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION                                                                                              | S/N \$   | 360.00               |                               |
| 2                               | TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS                                                                                                                                     | S/N \$   | 600.00               |                               |
| 3                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS                                                                                                                    | S/N \$   | 400.00               |                               |
| 4                               | TO CARRY OUT SPEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS                                                                                                                   | S/N \$   | 200.00               |                               |
| 5                               | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT , BATTERY MANAGER , FUSE AND RELAY TRAYS , ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$   | 1,400.00             |                               |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                | <b>:</b> | <b>\$</b>            | <b><u>2,960.00</u></b>        |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 3277 D**

| S/N                         | NATURE OF JOBS                                                                                                                                                                      |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 6                           | TO REMOVE AND REINSTALL REAR SEAT , BACK REST ,<br>HAT TRAY , ABCD PILLAR TRIMS , LUGGAGE<br>COMPARTMENT TRIMS. DISLODGE ROOF LINER AND<br>DISENGAGE CURTAIN AIRBAG ETC.            | S/N \$ | 1,400.00             | \$        | <b>480.00</b>                 |
| 7                           | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-<br>LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT<br>FOR DAMAGES                                                                       | S/N \$ | 350.00               | \$        | <b>280.00</b>                 |
| 8                           | TO DISMANTLE AND REINSTALL REAR BUMPER. TO<br>RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS<br>REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT<br>COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 5,600.00             | \$        | <b>2,500.00</b>               |
| 9                           | TO RESPRAY LHS REAR FENDER , LHS REAR DOOR , LHS<br>SILL PANEL , ROOD CHANNEL , DRAIN CHANNEL , DOOR<br>ENTRANCE AND REAR END PANELLING.                                            | \$     | 4,750.00             | \$        | <b>1,925.00</b>               |
| 10                          | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                                                       | S/N \$ | 192.00               | \$        | <b>192.00</b>                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                     | :      | <b>\$ 15,252.00</b>  | <b>\$</b> | <b>5,377.00</b>               |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJE 3277 D**

|                             |                            |     | DAMAGED PARTS & PRICES |         |           |
|-----------------------------|----------------------------|-----|------------------------|---------|-----------|
| S/N                         | PARTS DESCRIPTION          | QTY | S/NETT                 | REMARKS |           |
| 1                           | REAR SECTIONAL PART - LEFT | 1   | \$ 4,052.00            | \$      | 3,241.60  |
| 2                           | REAR WINDSCREEN            | 1   | \$ 1,154.00            |         |           |
| 3                           | REAR 1/4 GLASS - LH        | 1   | \$ 616.00              |         |           |
| 4                           | PRIMER                     | 1   | \$ 40.00               |         |           |
| 5                           | REAR DOOR - LH             | 1   | \$ 3,192.00            | \$      | 2,553.60  |
| 6                           | REAR DOOR OUTER SEAL - LH  | 1   | \$ 205.00              | \$      | 164.00    |
| 7                           | BONDING AGENT              | 1   | \$ 49.00               |         |           |
| 8                           | CLEANING SOLUTION          | 1   | \$ 68.00               |         |           |
| 9                           | APPLICATOR                 | 1   | \$ 8.00                |         |           |
| 10                          | REAR DOOR SEALING STRIP    | 1   | \$ 17.00               |         |           |
| 11                          | REAR ATTACHMENT PARTS      | 1   | \$ 860.00              |         |           |
| 12                          | REAR DOOR CATCH - LH       | 1   | \$ 120.00              |         |           |
| 13                          | 1/4 GLASS SEALANT          | S/N | \$ 100.00              |         |           |
| 14                          | ACRYLIC SEALANT            | S/N | \$ 180.00              | \$      | 180.00    |
| 15                          | CAVITY WAX                 | S/N | \$ 140.00              | \$      | 140.00    |
| 16                          | STONE CHIP                 | S/N | \$ 180.00              | \$      | 180.00    |
| 17                          | METAL FILLER POWER         | S/N | \$ 280.00              | \$      | 280.00    |
| 18                          | REAR WINDSCREEN SEALANT    | S/N | \$ 200.00              |         |           |
| 19                          | SUNDRIES                   |     | \$ 300.00              | \$      | 8.40      |
| <b>TOTAL SPARE PARTS</b>    |                            | :   | \$ 11,761.00           | \$      | 6,747.60  |
| <b>TOTAL LABOUR CHARGES</b> |                            | :   | \$ 15,252.00           | \$      | 5,377.00  |
| <b>GRAND TOTAL</b>          |                            | :   | \$ 27,013.00           | \$      | 12,124.60 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-27/07/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT