

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/OD/0499/2021/ZK
 DATE : 18-Jun-21
 WIP : 31921

Xiao Chen.

\$12124-60.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS AMELIA SANTOSA
 ADDRESS : 15 EVELYN ROAD

SINGAPORE 309311
 TELEPHONE : HP +65 90177169
 TYPE OF CLAIM : OWN DAMAGE CLAIM
 POLICY NO : 1800149049-02
 VEHICLE NO : SJE 3277 D
 MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
 MODEL YEAR : 24/12/2018
 ENGINE NO : CVK 072177
 CHASSIS NO : WAUZZZF48KN000861
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 6-Jun-21
 PLACE OF ACCIDENT : RESIDENCES @ EVELYN CONDOMINIUM

[Signature]

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 3277 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	X
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS	S/N \$ 600.00	X
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	S/N \$ 400.00	X
4	TO CARRY OUT SPEEAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	S/N \$ 200.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	X

SUB TOTAL LABOUR CHARGES

: \$ 2,960.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 3277 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC. X X	1,400.00	480 ✓
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	350.00	280 ✓
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	5,600.00	2500 ✓
9	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, ROOD CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	4,750.00	4750 3.5 x 2 = 550 = 1925 ✓
10	TO CARRY OUT DIAGNOSTIC CHECK	192.00	✓
TOTAL LABOUR CHARGES		\$ 15,252.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6641 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJE 3277 D

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
1	REAR SECTIONAL PART - LEFT <i>Dented</i>	1	\$ 4,052.00	✓	3241.60
2	REAR WINDSCREEN <i>3 New</i>	1	\$ 1,154.00	+	
3	REAR 1/4 GLASS - LH <i>Not Nec</i>	1	\$ 616.00	+	
4	PRIMER <i>Nec</i>	1	\$ 40.00	X	X
5	REAR DOOR - LH <i>Dented</i>	1	\$ 3,192.00	✓	2553.60
6	REAR DOOR OUTER SEAL - LH <i>Nec</i>	1	\$ 205.00	✓	164
7	BONDING AGENT <i>3</i>	1	\$ 49.00	✓	X
8	CLEANING SOLUTION <i>1 New</i>	1	\$ 68.00	✓	X
9	APPLICATOR	1	\$ 8.00	✓	X
10	REAR DOOR SEALING STRIP <i>3 New</i>	1	\$ 17.00	+	
11	REAR ATTACHMENT PARTS	1	\$ 860.00	+	
12	REAR DOOR CATCH - LH <i>3 New</i>	1	\$ 120.00	?	X
13	1/4 GLASS SEALANT <i>Nec</i>	S/N	\$ 100.00	+	X
14	ACRYLIC SEALANT <i>3</i>	S/N	\$ 180.00	✓	✓
15	CAVITY WAX <i>Nec</i>	S/N	\$ 140.00	✓	✓
16	STONE CHIP	S/N	\$ 180.00	✓	✓
17	METAL FILLER POWER	S/N	\$ 280.00	✓	✓
18	REAR WINDSCREEN SEALANT <i>Nec</i>	S/N	\$ 200.00	✓	X
19	SUNDRIES <i>Nec</i>	\$	300.00	?	8.40 ✓
TOTAL SPARE PARTS		:	\$ 11,761.00		
TOTAL LABOUR CHARGES		:	\$ 15,252.00		
GRAND TOTAL		:	\$ 27,013.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIM@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian G
: 23/06/21

: Not Authorised, 09 Days. *[Signature]*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT