

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0498/2021/ZK
DATE : 18-Jun-21
WIP : 31918

Xiao Chen.

\$3516.96.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/06/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS AMELIA SANTOSA
ADDRESS : 15 EVELYN ROAD
SINGAPORE 309311
TELEPHONE : HP +65 90177169
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800149049-02
VEHICLE NO : SJE 3277 D
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 24/12/2018
ENGINE NO : CVK 072177
CHASSIS NO : WAUZZZF48KN000861
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jun-21
PLACE OF ACCIDENT : OUTSIDE SGH

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NCRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 3277 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LID.	S/N \$ 360.00	X ✓ <i>[Signature]</i>
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
3	TO RESPRAY FRONT BUMPER.	\$ 900.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NDRA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJE 3277 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Reis</i>	1	\$ 1,787.00	*
2	FRONT BUMPER FIXING PARTS	1	\$ 587.00	*
3	FRONT BUMPER SECURING STRIP <i>3 x 4</i>	2	\$ 71.00	*
4	FRONT BUMPER GRILLE - CENTER <i>me</i>	1	\$ 196.00	*
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>me</i>	1	\$ 210.00	*
6	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 1,333.00	1065.60
7	FRONT BUMPER REFORCEMENT ABSORBER <i>cracked</i>	1	\$ 124.00	99.20 ✓
8	FRONT BUMPER REFORCEMENT <i>dented</i>	1	\$ 845.00	675.60 ✓
9	FRONT BUMPER TOP COVER <i>4</i>	1	\$ 127.00	*
10	CAUTION STICKER <i>1 x 4</i>	1	\$ 14.00	*
11	AIR-CONDITIONER STICKER <i>me</i>	1	\$ 8.00	*
12	FRONT RADIATOR BRACKET	1	\$ 137.00	*
13	FRONT BUMPER BRACKET - LH / RH	2	\$ 58.00	*
14	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER <i>me</i>	2	TBC	*
15	FRONT BUMPER PARKING AID SENSOR SEAL <i>2</i>	4	\$ 14.00	*
16	FRONT RADIATOR AIR GUIDE <i>4</i>	4	\$ 80.00	*
17	FRONT RADIATOR AIR GUIDE - UPPER <i>1</i>	1	\$ 16.00	*
18	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	✓
19	SUNDRIES <i>me</i>	\$	300.00	14.56 ✓
TOTAL SPARE PARTS		:	\$ 5,967.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 8,469.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian L
23/06/21

: Not Authorised, 038 days J.E.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROCESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT