

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0509/2021/ZK
DATE : 22-Jun-21
WIP : 32015

Veron.

\$5568.48.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/06/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR FENG LI YUAN
ADDRESS : BLK 130 SERANGOON AVE 3
#01-04
SINGAPORE 554479
TELEPHONE : HP +65 90372113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210056892
VEHICLE NO : SNA 2069 T
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : Q3 1.4 TFSI S tronic
ENGINE NO : CZD C41552
CHASSIS NO : WAUZZZF38M1126574
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jun-21
PLACE OF ACCIDENT : SERANGOON NEX SHOPPING MALL CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2069 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND INSTALL REAR PARKING AID AND REAR LID KICK SENSOR	S/N \$ 360.00	X
2	TO RENEW LHS 1/4 GLASS TO FACILLIATE FENDER RENEWAL	S/N \$ 300.00	X
3	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	S/N \$ 400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	S/N \$ 200.00	X
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENFW WHERE NECESSARY	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 2,660.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2069 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT , BACK REST , HAT TRAY , ABCD OILLAR TRIMS , LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN ATRRAG, ETC	S/N \$ 1,400.00	X
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 ✓
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00	750 ✓
9	TO RESPRAY LHS REAR FENDER , LHS REAR DOOR , LHS SILL PANEL , ROOF CHANNEL , DRAIN CHANNEL , DOOR ENTRANCE AND REAR END PANELLING	\$ 5,400.00	1200 ✓
	Door Handle 100		
10	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 16,452.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2069 T

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR PANEL - LH <i>Repair</i>	1	\$ 3,388.00	X
2	REAR SIDE WINDOW - LH <i>Ne m</i>	1	\$ 614.00	X
3	PRIMER <i>Ne m</i>	1	\$ 20.00	+
4	REAR DOOR - LH <i>Dented</i>	1	\$ 2,909.00	✓ 2327.20
5	REAR DOOR OUTER SEAL - LH <i>Ne</i>	1	\$ 135.00	✓ 108
6	REAR DOOR ATTACHEMNT PARTS <i>Ne m</i>	1	\$ 311.00	X
7	REAR DOOR CATCH - LH <i>Not see</i>	1	\$ 120.00	→ X
8	REAR DOOR LOWER COVER - LH <i>cut</i>	1	\$ 257.00	✓ 205.20
9	REAR DOOR HANDLE - LH <i>cut</i>	1	\$ 198.00	✓ 158
10	REAR DOOR HOUSING CAP - LH <i>Ne m</i>	1	\$ 27.00	+
11	REAR WHEEL SPOILER - LH <i>Repair</i>	1	\$ 39.00	+
12	REAR WHEEL HOUSE LINER - LH	1	\$ 241.00	+
13	REAR WHEEL HUOSE LINER ATTACHMENT - LH / RH <i>Ne m</i>	1	\$ 101.00	+
14	REAR WHEEL ARCH COVER - LH / RH <i>LH cut</i>	2	\$ 536.00 268.214.40	
15	1/4 GLASS SEALANT	S/N	\$ 100.00	+
16	ACRYLIC SEALANT	S/N	\$ 180.00	+
17	CAVITY WAX	S/N	\$ 140.00	+
18	STONE CHIP	S/N	\$ 180.00	+
19	METAL FILLER POWLR	S/N	\$ 280.00	+
20	SUNDRIES <i>Ne m</i>		\$ 300.00	? 4.48
TOTAL SPARE PARTS		:	\$ 10,076.00	
TOTAL LABOUR CHARGES		:	\$ 16,452.00	
GRAND TOTAL		:	\$ 26,528.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan hiny
SURVEYED DATE : 23/06/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : not Authorised, 05 Days. 04 Days.
Slp.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT