

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0519/2021/TF
DATE : 23-Jun-21
WIP : 32214

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

20-Aug-21

OWNER'S NAME : MR. LIM KAR HENG DENNIS
ADDRESS : 50 CHOACHU KANG NORTH 7
#06-09
SINGAPORE 689527
TELEPHONE : HP +65 96254063
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210027627
VEHICLE NO : **SLV 4898 S**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 19/3/2021
ENGINE NO : DEM 025395
CHASSIS NO : WAUZZZF45MN000903
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jun-21
PLACE OF ACCIDENT : 61 IRRRAWADDY ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 2,772.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,233.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 358.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 262.00	
6	FRONT RADIATOR GRILLE CLOSING ELEMENT	1	\$ 262.00	
7	FRONT RADIATOR GRILLE	1	\$ 1,580.00	
8	FRONT BUMPER FORM	1	\$ 189.00	
9	FRONT BUMPER CARRIER	1	\$ 845.00	
10	FRONT BUMPER TOP COVER	1	\$ 127.00	
11	CAUTION STICKER	1	\$ 14.00	
12	A/C STICKER	1	\$ 8.00	
13	FRONT LOCK CARRIER BRACKET	1	\$ 137.00	
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00	
15	FRONT BONNET	1	\$ 3,246.00	\$ 2,596.80
16	FRONT BONNET ATTACHMENT PARTS	1	\$ 412.00	
17	FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 84.00	\$ 65.68
18	FRONT HEADLIGHT - RH	1	\$ 7,685.00	
19	FRONT RADIATOR AIR GUIDE - RH / RH / UPPER	3	\$ 76.00	
20	FRONT NO. PLATE	S/N	\$ 60.00	
21	SUNDRIES		\$ 192.00	
TOTAL SPARE PARTS		:	\$ 14,713.00	\$ 2,662.48
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 2,772.00
GRAND TOTAL		:	\$ 19,835.00	\$ 5,434.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-27/07/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT