

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0519/2021/TF  
**DATE** : 23-Jun-21  
**WIP** : 32214

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/21**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR. LIM KAR HENG DENNIS  
**ADDRESS** : 50 CHO A CHU KANG NORTH 7  
#06-09  
SINGAPORE 689527  
**TELEPHONE** : HP +65 96254063  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210027627  
**VEHICLE NO** : **SLV 4898 S**  
**MODEL CODE** : A4 SEDAN 2.0 TFSI S TRONIC  
**MODEL YEAR** : 19/3/2021  
**ENGINE NO** : DEM 025395  
**CHASSIS NO** : WAUZZZF45MN000903  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 19-Jun-21  
**PLACE OF ACCIDENT** : 61 IRRAWADDY ROAD

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S**

| S/N                         | NATURE OF JOBS                                                                                                                                      | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING. LTD | S/N \$ 480.00        | ✓                          |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.                                                                              | S/N \$ 350.00        | X                          |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.               | \$ 2,100.00          | 1000                       |
| 4                           | TO RESPRAY FRONT BUMPER AND BONNET.                                                                                                                 | \$ 2,000.00          | 1100                       |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                      | S/N \$ 192.00        | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                     | <b>: \$ 5,122.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S**

|                             |                                                              |     | DAMAGED PARTS & PRICES |         |  |
|-----------------------------|--------------------------------------------------------------|-----|------------------------|---------|--|
| S/N                         | PARTS DESCRIPTION                                            | QTY | S/NETT                 | REMARKS |  |
| 1                           | FRONT BUMPER <i>Repair</i>                                   | 1   | \$ 2,233.00            | +       |  |
| 2                           | FRONT BUMPER FIXING PARTS                                    | 1   | \$ 358.00              | +       |  |
| 3                           | FRONT BUMPER SECURING STRIP                                  | 2   | \$ 71.00               | x       |  |
| 4                           | FRONT BUMPER GRILLE - CENTER                                 | 1   | \$ 196.00              | x       |  |
| 5                           | FRONT BUMPER CLOSING ELEMENT                                 | 1   | \$ 262.00              | x       |  |
| 6                           | FRONT RADIATOR GRILLE CLOSING ELEMENT                        | 1   | \$ 262.00              | +       |  |
| 7                           | FRONT RADIATOR GRILLE                                        | 1   | \$ 1,580.00            | x       |  |
| 8                           | FRONT BUMPER FORM                                            | 1   | \$ 189.00              | +       |  |
| 9                           | FRONT BUMPER CARRIER                                         | 1   | \$ 845.00              | +       |  |
| 10                          | FRONT BUMPER TOP COVER                                       | 1   | \$ 127.00              | +       |  |
| 11                          | CAUTION STICKER                                              | 1   | \$ 14.00               | +       |  |
| 12                          | A/C STICKER                                                  | 1   | \$ 8.00                | x       |  |
| 13                          | FRONT LOCK CARRIER BRACKET                                   | 1   | \$ 137.00              | +       |  |
| 14                          | FRONT BUMPER SUPPORT - LH / RH                               | 2   | \$ 58.00               | +       |  |
| 15                          | FRONT BONNET <i>Dented</i>                                   | 1   | \$ 3,246.00            | ✓       |  |
| 16                          | FRONT BONNET ATTACHMENT PARTS <i>new</i>                     | 1   | \$ 412.00              | +       |  |
| 17                          | FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i> | 3   | \$ 84.00               | ✓       |  |
| 18                          | FRONT HEADLIGHT - RH <i>new</i>                              | 1   | \$ 7,685.00            | +       |  |
| 19                          | FRONT RADIATOR AIR GUIDE - RH / RH / UPPER <i>new</i>        | 3   | \$ 76.00               | +       |  |
| 20                          | FRONT NO. PLATE <i>new</i>                                   | S/N | \$ 60.00               | +       |  |
| 21                          | SUNDRIES                                                     |     | \$ 192.00              | ?       |  |
| <b>TOTAL SPARE PARTS</b>    |                                                              |     | <b>\$ 14,713.00</b>    |         |  |
| <b>TOTAL LABOUR CHARGES</b> |                                                              |     | <b>\$ 5,122.00</b>     |         |  |
| <b>GRAND TOTAL</b>          |                                                              |     | <b>\$ 19,835.00</b>    |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

*Please allow  
reshave of bonnet.*



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lij

SURVEYED DATE

: 23/06/21.

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT