

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305475123
Date 25/06/21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr NAZ
Vehicle Reg No. SHA7104M Date of Accident : 23/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ECICS --- SJL746A
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,105.16
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost \$1,735.16
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : [Signature]
Name : NAZ LKK
Date : 9/7/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305475123
 REGN NO : SHA7104M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 25.10.2019
 DATE/TIME IN : 23.06.2021 12:45
 ACCIDENT DATE : 23.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0002	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00
0005	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	0.20	50.00
0006	FNPS	NUMBER PLATE W/CASING	1 N	50.00	0.02-	50.00
0007	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52

SUB-TOTAL : 1,105.16

JOB NATURE

0000	PB	PANEL BEATING (SHA7104M)	350.00
0001	SP	SPRAYPAINT CHARGE	250.00
0002	L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 630.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305475123
REGN NO : SHA7104M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 23.06.2021 12:4
ACCIDENT DATE : 23.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,735.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7104M

DATE: 23. June 2021

Jumani

MAKE HYUNDAI

DOA: 23. Jun. 2021

ECICS

MODEL IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$98.80
1	REAR BUMPER TOW COVER			\$459.40
1	REAR BUMPER ASSY			\$451.25
1	REAR BUMPER CENTRE MLDG			\$22.00
10	REAR BUMPER CLIP			\$394.80
1	REAR BUMPER BEAM			\$201.50
1	REAR FOG LAMP			\$40.50
1	ANTENNA - SMARKKEY			\$1,668.25
				\$1,668.25
				\$333.65
				\$1,334.60
				\$180.00
				\$50.00
				\$230.00
				\$400.00
				\$300.00
				\$80.00
				\$780.00
				\$2,344.60

SUB TOTAL

LESS 25%

20%

DISCOUNTED TOTAL

WINDSCREEN SEALANT

REVERSE SENSOR

REAR BUMPER MAT

Labour Charge

PANEL BEATING

SPRAY PAINT

REMOVE/REFIX REVERSE SENSOR

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer

Signature:

Date:

NAZUK
24/6/2021 1545
P/P 12 DMOJ
CHECK ITEM PHOTO
AFTER REPAIR PHOTO