

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007000/UPA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100246219
Claimant Vehicle No :	FBC2347Y	Insured Vehicle No :	SFH8286B
Date of Loss:	15/06/2021	Nature of Claim:	TP
		Claim No:	6907513647SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC2347Y	Engine No:	JC33E5203032
Make & Model:	HONDA ANF125, 125cc (A)	Chassis No:	MLHJC33A465203032
Reg. Date:	24/12/2007 (Man. Year: 2005)	Odometer:	65474 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,427.00	691.50	2,735.50	79.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	480.00	530.00	52.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,437.00	1,171.50	3,265.50	73.60
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	4,437.00	900.00	3,537.00	79.72
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,000.00		

INSPECTION

Date of Assignment:	24/06/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	24/06/2021 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Not Necessary	280.00 FL	*- FL
2	2		*FORK OUTER TUBES	Not Necessary	290.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
4	1		*FRONT SPORT RIM	Not Necessary	280.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	42.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
7	1		*SIDE MIRROR (N/S)	Cut	96.00 FL	*60.00 FL
8	1		*HANDLE -BAR	Serviceable	80.00 FL	*- FL
9	1		*HANDLE -BAR ENDS (N/S)	Cut	95.00 FL	*38.00 FL
10	1		*SET HAND GRIP	Not Necessary	50.00 FL	*- FL
11	1		*FRONT FOOTREST BRACKET	Bent	55.00 FL	*55.00 FL
12	1		*FRONT FOOTREST RUBBERS	Torn	56.00 FL	*56.00 FL
13	1		*GEAR PEDAL	Bent	42.00 FL	*42.00 FL
14	2		*REAR FOOTREST	Cut (1 PCS ONLY)	76.00 FL	*56.00 FL
15	1		*REAR FOOTREST BRACKET	Not Necessary	130.00 FL	*- FL
16	1		*REAR SIGNALS -L/H	Cut	140.00 FL	*78.00 FL
17	1		*FAIRING ASSY	Repair	685.00 FL	*- FL
18	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
21	1		*SET STEERING CONE BEARING	Not Necessary	85.00 FS	*- FS
22	1		*REAR BOX	Cut	380.00 FS	*180.00 FS
23	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
24	1		*SET STICKER	Not Necessary	120.00 FS	*- FS
25	1		*E.R.P IU	Cracked	180.00 FS	*165.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,689.00	730.00
- List Item Discount on L Items 10.00/10.00% (S\$)					262.00	38.50
Total Parts (S\$)					3,427.00	691.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING	New	30.00	30.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO SPRAY PAINTING	New	480.00	200.00
4	TO PROVIDE LABOUR	New	420.00	250.00
Gross Labour Cost (\$\$)			1,010.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >