

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref	1	305475091	Via Fax	1
Date	:	24.06.21	Your Insured	: SIA 4473 T.
Time of Fax	:	Email	Date of Acc	: 23.06.21

Attn: Motor Claims Department

AIG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH _ 33067.

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Ms. Loke Wei Yieng (yy) • Jumani Bin Masudin • Lim Tien Siong • Chiang Liat Choon Tel: 62148355 or HP: 86285336 Tel: 6214 8315 or HP: 9635 5305 Tel: 6214 8398 or HP: 9635 8546 • Chiang Liat Choon Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA3306Z

Make :

Model

: Toyota

: Prius (G4)

Date: 24.06.2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	1 FRT FENDER SHIELD			\$198.5
	1 FRONT FENDER SUB ASSY			\$945.3
	1 FRONT FENDER HOUSING LH			\$958.3
	1 FRT FENDER SHIELD CLIPS			\$38.0
	1 FRONT FENDER HYBRID EMBLEM LH			\$86.5
	1 FRT PILLAR UPPER LH			\$96.0
	1 FRONT BUMPER COVER			\$499.9
	1 FRONT BUMPER SIDE BRACKET LH			\$82.3
1	0 FRONT BUMPER CLIPS			\$22.0
	1 FRONT BUMPER SIDE COVER LH			\$172.5
	1 FRONT BUMPER CENTRE GRILLE			\$301.9
	1 FRONT BUMPER LOWER GRILLE			\$166.9
	1 FOG LAMP LH			\$920.0
8	FRONT BUMPER SIDE RETAINER LH			\$77.0
	1 HEADLAMP UNIT ASSY LH			\$2,735.2
	1 HEADLAMP PANEL LH			\$240.
	TOP PANEL SIDE LH			\$145.9
	1 FRT SUSPENSION LOWER ARM LH			\$637.
	FRT SHOCK ABSORBER LH			\$401.8
	ABSORBER TOP MOULDING LH			\$196.2
	STABILIZER BAR LH			\$360.0
	ISTABILIZER LINK LH			\$199.0
	LOWER BALL JOINT LH			\$199.9
	ITIE ROD END LH			\$159.3
	KNUCKLE STEERING LH			\$580.8
	IFRT WHEEL RIM LH			\$1,570.5
	SUB TOTAL			\$11,991.5
	LESS 25%		_	\$2,997.8
	DISCOUNTED TOTAL			\$8,993.6
	FRT TYRE LH			\$216.0
				\$216.0
	Labour Charge			
	PANEL BEATING			\$1,750.0
- 1	SPRAY PAINTING CHARGE			\$600.0
	WIRING CHARGE			\$50.0
	TUFF KOTE			\$60.0
	FRT WHEEL ALIGNMENT			\$80.0
	REMOVE & REFIX FRT UNDECARRIAGE			\$400.0

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	TOTAL LABOU	JR		\$2,940.00
	ESTIMATE TOTA	AL		\$12,149.63

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 24.06.2021 09:49

Page : 1

JOB CARD JC NO.: Team: ARC Repair TP(CLSO)1 Sales Order: 4092241 30547509 MILEAGE CUSTOMER REGN NO .: SHA3306Z COMFORT TRANSPORTATION PTE LTD FUEL /IR/MS MAKE : 7010045 TOYOTA SUSTOMER NO. E.....1/2...... 383 SIN MING DRIVE DATE/TIME IN ADDRESS MODEL PRIUS HYBRID(G4) 23.06.2021 09:5 Singapore SINGAPORE 575717 65508755 TARGET DATE YR OF MANU. 25.07.2017 (P) CHASSIS CODE COMPLETION DATE/TIME: JTDKB3FU103562941 DISCOUNT CARD NO.


JOB DESCRIPTION

Accident Date: 23.06.2021 NATURE: 3P 23.06.2021

S/NO

LABOR CODE

DESCRIPTION



					4
HECKED & P	ASSED OUT BY:		_		
	SERVICE ADVISOR			CUSTOMER'S SIGNATURE	
inowledgemer	nt Slip		Exit Pass		
ne: No.: icle No.:	SHA3306Z	YY	Vehicle No.: SHA33062	7.J	,
ne of Service	Advisor	Signature/Date	Name of Service Advisor	Date	
pe returned to Service Reception upon collection			To be kept by Security Guard		