

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007010/KRS3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070102770	
Claimant Vehicle No :	SMR1270G	Insured Vehicle No :	SCV8822R	
Date of Loss:	12/06/2021	Nature of Claim:	TP	Claim No: 9281816032SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1270G		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B6020435
Reg. Date:	20/12/2019 (Man. Year: 2019)	Chassis No:	GK82100356
Colour:	Metallic Red	Odometer:	105783 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,777.04	2,542.64	1,234.40	32.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	965.00	1,355.00	58.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,097.04	3,507.64	2,589.40	42.47
Approved Total (Overridden) (S\$)		2,800.00		

(S\$)	6,097.04	2,800.00	3,297.04	54.08
+ GST 7.00/7.00% (S\$)	426.79	196.00	230.79	54.08
Nett Amount (S\$)	6,523.83	2,996.00	3,527.83	54.08
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,243.45		

INSPECTION

Date of Assignment: 22/06/2021

Date Inspected: 22/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.70 FL	*1,193.70 FL
2	1		*REAR TAILGATE H LOGO	Necessary	58.00 FL	*58.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE INNER RUBBER	Serviceable	188.50 FL	*- FL
7	1		*REAR BUMPER	Buckled / Dented	1,150.60 FL	*1,150.60 FL
8	1		*REAR BUMPER SIDE RETAINER	Serviceable	77.00 FL	*- FL
9	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
10	1		*REAR BUMPER GARNISH	Mtg Cracked	195.50 FL	*195.50 FL
11	1		*REAR END PANEL	Repair	685.00 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	285.50 FL	*155.50 FL
13	1		*SET REAR PARKING SENSOR	Serviceable	280.00 FS	*- FS
14	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
15	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,618.80	3,168.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					841.76	625.66
Total Parts (\$\$)					3,777.04	2,542.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	100.00	15.00
3	TUFFKOTE	New	100.00	30.00
4	SPRAY PAINTING	New	1,000.00	400.00
5	LABOUR CHARGES	New	1,000.00	400.00
Gross Labour Cost (S\$)			2,320.00	965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >