

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

12/06/2021

Owner: LIM HUNG TONG

ESTIMATE TO REPAIR HONDA SHUTTLE - SMR1270G

1pc	rear tailgate	\$ 1,193.70
1pc	rear tailgate "H" logo	\$ 58.00
1pc	rear tailgate "SHUTTLE" emblem	\$ 55.00
1pc	rear tailgate "HYBRID" emblem	\$ 75.00
1pc	rear tailgate windscreen moulding	\$ 195.00
1pc	rear tailgate inner rubber	\$ 188.50
1pc	rear bumper	\$ 1,150.60
2pcs	rear bumper side retainer @\$38.50	\$ 77.00
10pcs	rear bumper clip @\$5.00	\$ 50.00
1pc	rear bumper garnish	\$ 195.50
1pc	rear end panel	\$ 685.00
1pc	rear end panel inner garnish	\$ 285.50

less 20%

\$ 4,208.80
\$ 841.76
<u>\$ 3,367.04</u>

1set	rear parking sensor	s.nett \$ 280.00
1set	rear number plate & casing	s.nett \$ 50.00

remove & refit rear windscreen glass	\$ 120.00
sealant	\$ 80.00
wiring	\$ 100.00
tuffkote	\$ 100.00
spray painting	\$ 1,000.00
labour charges	\$ 1,000.00
Total	<u><u>\$ 6,097.04</u></u>

