

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

A19
22/06/21
10.30am

12/06/2021

Owner: LIM HUNG TONG

ESTIMATE TO REPAIR HONDA SHUTTLE - SMR1270G

1pc	rear tailgate	B1	\$ 1,193.70	✓
1pc	rear tailgate "H" logo	m	\$ 58.00	✓
1pc	rear tailgate "SHUTTLE" emblem	m	\$ 55.00	✓
1pc	rear tailgate "HYBRID" emblem	m	\$ 75.00	✓
1pc	rear tailgate windscreen moulding	m	\$ 195.00	✓
1pc	rear tailgate inner rubber	sm	\$ 188.50	✓
1pc	rear bumper	Bu 101	\$ 1,150.60	✓
2pcs	rear bumper side retainer @\$38.50	sm	\$ 77.00	X
10pcs	rear bumper clip @\$5.00	m	\$ 50.00	✓
1pc	rear bumper garnish	mycmt	\$ 195.50	✓
1pc	rear end panel	r	\$ 685.00	X
1pc	rear end panel inner garnish 135.50	my dit	\$ 285.50	✓
			\$ 4,208.80	
less 20%			\$ 841.76	
			\$ 3,367.04	

1set	rear parking sensor	sm	s.nett \$ 280.00	X
1set	rear number plate & casing		s.nett \$ 50.00	X

remove & refit rear windscreen glass	\$ 120.00	✓
sealant	\$ 80.00	✓
wiring	\$ 100.00	156
tuffkote	\$ 100.00	301
spray painting	\$ 1,000.00	4001
labour charges	\$ 1,000.00	4001
Total	\$ 6,097.04	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: