

ASS. REC. BY:

REF:

TU / 21007013/kb
GRB

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HN 9888A

Yr Regn:

08.20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Provs

c.c

1798

Colour

M.P. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

76188

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU203091243

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order

Jammed / Leaked / Burnt or

Brake: In order

Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailan

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/6/21

D.O.I.

25/6/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ

28/6 @ 700.88 Cash

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9988A**AAD2106-***Not Authored**Henry Bepaim**8700.88*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 JUN 2021

SHD9988A

JTDKB3FUX03091243

TOYOTA

PRIUS GEN 4

24/06/2021

III

03/08/2020

PART	LIST
1 COVER, REAR BUMPER	\$ R 485.60 X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ R 332.70 X
1 GUARD, REAR BUMPER, CENTER	\$ R 374.50 ✓
1 COVER, REAR BUMPER, LOWER	\$ R 22.00 X
1 RETAINER, REAR BUMPER SIDE, LH	\$ R 132.60
1 RETAINER, REAR BUMPER SIDE, RH	\$ R 132.60
1 REFLECTOR ASSY, REFLEX, LH	\$ R 39.00
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ R 651.00
1 COVER, DECK TRIM, REAR	\$ R 126.70
1 COVER, FLOOR UNDER, NO.2 (RH)	\$ R 241.90
1 COVER, FLOOR UNDER, NO.1 (LH)	\$ R 175.10
1 COVER, REAR FLOOR (CTR)	\$ R 229.90
1 PANEL SUB-ASSY, BACK DOOR	\$ R 1,147.80
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ R 913.60
1 STAY ASSY, BACK DOOR, LH	\$ R 242.50
1 STAY ASSY, BACK DOOR, RH	\$ R 242.50
1 HINGE ASSY, BACK DOOR, LH	\$ R 61.00
1 HINGE ASSY, BACK DOOR, RH	\$ R 61.00
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ R 47.90
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ R 54.60
1 PLATE, BACK DOOR NAME, NO.1	\$ R 54.60

TOTAL	\$	5,769.10
25%	\$	1,442.28
	\$	4,326.83

Trans-cab Auto Services Pte Ltd**AAD2106-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9988A**Special Nett**

1SET PARKING AID	\$	Pen	700.00	}	X
1SET REAR BUMPER CLIP	\$	nn	85.00		
1 BUMPER CENTRE GUARD CLIP	\$	nn	80.00		
1 REAR BUMPER PROTECTOR	\$	Pen	180.00		
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00		
1 BOOT STICKER TRANSCAB	\$	nn	100.00		
1 BOOT STICKER 65553333	\$	nn	100.00		
2 WINDSCREEN SEALANT	\$	nn	150.00		
1 WINDSCREEN MOULDING	\$	nn	200.00		
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00		
TOTAL	\$		1,120.00		
TOTAL PARTS	\$		5,446.83		

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	2201
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X

Trans-cab Auto Services Pte Ltd**AAD2106-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9988ATo reinstall rear bumper parking sensor. \$ *~ ~* 170.00 XTo Check Electrical Lighting Concerned. \$ *~ ~* 170.00 X**TOTAL** \$ **4,840.00****Over All Total** \$ **10,286.83****(PART-BY-PART) Repair Days**~~10 Days~~*1 1/2 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: