

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Estimation

Date 23/6/2021
Vehicle SMY 12E
Make/Model MINI JOHN COOPER
WORKS GP AUTO
Chassis No. WMWXX920002N19210

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT BONNET / DD	1	\$2795	1,400 -
2	FRONT BONNET HEADLAMP OUTER RING RH ? XSVL	1	\$316	-
3	FRONT BONNET CENTER VENT ? XSVL	1	\$275	-
4	FRONT BONNET LOGO / NEL	1	\$110	70 -
5	FRONT GRILLE ? XSVL	1	\$552	-
6	FRONT GRILLE CENTER GARNISH ? XSVL	1	\$102	-
7	FRONT GRILLE TOW COVER XSVL / DEF	1	\$80	-
8	FRONT HEADLAMP L+R ? R/CRK LXSVL	1	\$375	1,700 -
9	FRONT HEADLAMP BALAST L+R ? XSVL	1	\$978	-
10	FRONT HEADLAMP BRACKET L+R ? LXSVL R-DEF	1	\$175	86 -
11	FRONT BUMPER / DEF	1	\$1769	800 -
12	FRONT BUMPER RETAINER RH ? / DEF	1	\$97	-
13	FRONT BUMPER FOG LAMP GRILLE RH / DEF	1	\$159	-
14	FRONT BUMPER CENTER GRILLE ? XSVL	1	\$210	-
15	FRONT BUMPER CENTER GRILLE OUTER GARNISH ? XSVL	1	\$170	-
16	FRONT BUMPER SIDE GRILLE RH ? / DEF	1	\$95	-
17	FRONT BUMPER LOWER GARNISH RH ? / SCR	1	\$120	-
18	FRONT BUMPER WEATHERSTRIP CENTER ? XSVL	1	\$135	-
19	FRONT BUMPER WEATHERSTRIP RH ? XSVL	1	\$192	-
20	FRONT BUMPER BRACKET RH ? XSVL	1	\$307	-
21	FRONT BUMPER SPONGE ? / DEF	1	\$110	-
22	FRONT BUMPER REINFORCEMENT BAR ? / DD	1	\$473	-
23	FRONT SENSOR SET ? / not working	1	\$350	280 -
24	FRONT FENDER RH / DD	1	\$1200	450 -
25	FRONT FENDER TOP WEATHERSTRIP ? XSVL	1	\$105	-
26	FRONT FENDER SIDE CARBON FIBER / CRK	1	\$1025	900 -
27	FRONT FENDER COWLING RH ? / TN	1	\$195	-
28	FRONT SUPPORT PANEL ? XSVL	1	\$872	-
29	FRONT SUPPORT PANEL TOP STOPPER RH ? XSVL	1	\$51	-
30	FRONT AIR CON CONDENSER ? / DEF	1	\$1765	1,050 -
31	FRONT RADIATOR ? XSVL	1	\$1590	-
32	FRONT AIR CON FAN COWLING ASSY ? XSVL	1	\$597	-
33	FRONT WIPER WASHER TANK ? / DEF	1	\$165	-
34	FRONT RADIATOR RH ? / DEF	1	\$1355	500 -
35	FRONT RADIATOR BRACKET RH ? XSVL	1	\$126	-

22360 8,730

