					C	OMFORTDELGRO				
Our J	ob Re	f No :	305475088		ENGINEERING					
Date :			25/06/21		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969					
FINA	LIZAT	ION FORM			Fax: (	<u>ģ546 8156</u>				
To	: <b>LKK</b>				Fax:					
Attn	Attn: Mr Naz									
Vehicle Reg No. : SHC1						22.06.21				
The s	urvey	and estimates of	f the repairs of the above-r	nentioned vehicle	are as follows	:-				
1.	The	repair job shall bi	ill to:	NTUC	GBE7574P					
2.	The	finalized amount	shall be:							
	(a)	Spare Parts af	ter List discount							
	(b)	Labour Charge	s							
		Total for Part-	By-Part Repair Cost							
	(c.)	Lumpsum Rep	air (if applicable)							
	` '		sum repair cost after Less:	20%		\$850.00				
		Final Lumpsu	m Repair Cost							
3.	Estin	nated normal per	iod for repairs:	wo	working days.					
4.	We s	hall treat the ab	ove amount as Correct a	and Confirmed if	there is no re	ply from you within 7				
<b>5</b> .	Than	k you for your as	sistance.	We confirm the estimates and finalized amount						
	Sinne	<b></b>	S	Siç	gnature :	H				
Signature :			FYY	Na	me :	VAZ ÜKK				
				—— Da	ite :	917(202)				
	Fax	: 6546815								
or O	TICIAL	Use Only		Document						
		ltem	Amount	Attached Yes or No	Confirm By (Signature)	Remarks				
. Rental Rate P/Day				YES						
		ncome Paid		NO						
3. Sui	vey F	966								
I. LTA Search Fee			\$7.49 / \$2.00							
<ol> <li>Medical Fees (on behalf of driver, if applicable)</li> </ol>										
3 Ov	errun									
Remar	ks:									

## COMFORT TRANSPORTATION PTE LTD

## **REPAIR ESTIMATE**

Vehicle No.: SHC1745S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 24/06/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Passed plant I Inform	Туре	Unit Price	Amount	
acy	The second secon			\$459.40	
	1 REAR BUMPER COVER			\$22.00	Ι.
	10 REAR BUMPER CLIPS			\$451.25	/
	1 REAR BUMPER CENTRE MOULDING ASSY			\$394.80	1
	1 REAR BUMPER REINFORCEMENT			\$201.50	X
	1 REAR BUMPER FOG LAMP				1
	SUB TO	AL		\$1,528.95	1
	LESS 2			\$305.79	4
	DISCOUNTED TO			\$1,223.16	
	Diocontain 1				1
				\$50.00	
	1 REAR NUMBER PLATE WITH TRIM COVER		-10%		
	1 REAR BUMPER REVERSE SENSOR		-10%		
	TREAK BUMPER REVERSE SENSOR			\$230.00	4
	Labour Charge			\$400.00	1
	PANEL BEATING			\$300.00	
	SPRAY PAINTING CHARGE			\$50.00	
	WIRING CHARGE			\$80.00	
	REMOVE/REFIX REVERSE SENSOR			\$60.00	1
				\$830.00	$\exists$
	TOTAL LABO	UK		\$000.00	+
				\$2,283.10	6
	ESTIMATE TO	AL		Ψ2,230.11	Ħ

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZLKK
24/6/2021 1530
LIS
2 DAYS
CHECK ITEM PHOTOS
AFTEL REPORT PHOTOS

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: