

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC1745S

Date: 24/06/2021

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER FOG LAMP			\$201.50
	<b>SUB TOTAL</b>			\$1,528.95
	<b>LESS 20%</b>			\$305.79
	<b>DISCOUNTED TOTAL</b>			<b>\$1,223.16</b>
1	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$50.00
1	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				<b>\$230.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	WIRING CHARGE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	<b>TOTAL LABOUR</b>			<b>\$830.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,283.16</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK  
24/6/2021 1530  
LIS  
2 DAYS  
CHECK ITEM (PHOTO)  
AFTER REPAIR (PHOTO)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: