

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

12.07.2021

Lian Beng Engineering & Machinery Pte Ltd

REPAIR ESTIMATE FOR SCANIA P400 - XD 7790 B

1 pc	LH front side bumper	/	DO	REC
4 pc	LH front side bumper bolts	/		
1 pc	LH headlamp assy	/	BR	
1 pc	LH front signal lamp assy	/	BR	
1 pc	LH headlamp top garnish	/	BR	
1 pc	LH headlamp side garnish	X	nn	
1 pc	LH front lower step panel	/	BT	
1 pc	LH front lower step panel bracket	X	nn	
1 pc	LH front lower step panel garnish	X	nn	
1 pc	LH front upper step panel	/	CUT	
1 pc	LH front upper step panel bracket	X	nn	
1 pc	LH front upper step panel lamp	/	BR	
1 pc	LH front upper step panel garnish	/	CUT	
1 pc	LH front arch garnish - front	/	CUT	
1 pc	LH front arch garnish - rear	X	nn	
1 pc	LH front arch garnish center joint	X	nn	
1 pc	oil filter housing	X	nn	

1,613.20	1113
18.00	12
915.40	
481.70	198
341.20	
168.20	
609.90	424
180.50	
289.50	
609.90	424
138.90	
53.00	
483.20	191
862.70	
822.50	
35.40	
2,743.10	
10,366.30	
Less 10%	
1,036.63	
9,329.67	

41494-10

-107,

4244-69

- 1) Check electrical wirings and headlamp focus.
- 2) Repair accident damages and renew approved parts.
- 3) Spray painting on accident affected portions.
- 4) Tuff kote on accident affected portions.

60.00	30
1,080.00	409
1,080.00	300
100.00	30
\$ 11,649.67	

Steve CLKK

12/7/21, 10:00am

Wu RL
L/S

P- 4244-69

L- 760

4804-69

L/S- 3843.75

= 3850

My AL sy
S Lys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: