

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

12.07.2021

Lian Beng Engineering & Machinery Pte Ltd

REPAIR ESTIMATE FOR SCANIA P400 - XD 7790 B

1 pc	LH front side bumper		1,113.00
4 pc	LH front side bumper bolts	4.50	12.00
1 pc	LH headlamp assy		915.40
1 pc	LH front signal lamp assy		198.00
1 pc	LH headlamp top garnish		341.20
1 pc	LH headlamp side garnish		
1 pc	LH front lower step panel		424.00
1 pc	LH front lower step panel bracket		
1 pc	LH front lower step panel garnish		
1 pc	LH front upper step panel		424.00
1 pc	LH front upper step panel bracket		
1 pc	LH front upper step panel lamp		53.00
1 pc	LH front upper step panel garnish		191.00
1 pc	LH front arch garnish - front		862.70
1 pc	LH front arch garnish - rear		822.50
1 pc	LH front arch garnish center joint		
1 pc	oil filter housing		

5,356.80

Less 10%

535.68

4,821.12

- | | | |
|----|---|--------|
| 1) | Check electrical wirings and headlamp focus. | 30.00 |
| 2) | Repair accident damages and renew approved parts. | 400.00 |
| 3) | Spray painting on accident affected portions. | 300.00 |
| 4) | Tuff kote on accident affected portions. | 30.00 |

\$ 5,581.12
