

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
MR CHEONG	Cust No/Name	/PHILIP CHEONG SANG LEE			
, •	Reg No/Reg Date	SMF4546E / 13/11/201			
BLK 521 JELAPANG RD	Date In/Mileage	25/06/2021/ 0			
#05-161 SINGAPORE 670521	Chassis No	KNAF3416MK5019989			
31NGAPURE 0/0321	Engine No	G4FGJH709397			
Contact No 96231084	Make/Mode1	KIA/CERATO 1.6 A SR SX G335			
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00081	Cash	25/06/2021/ 11:39		442 / CocoLu		35217		
		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
		R, REAR AIRDAM, BOOTL	.ID, REAR E	ND PANEL				
	AMP HOUS:	ING LH & RH						
E PNT88000	THOTALI	DEAD AZDDAM						100.00
E PNT88000	INSTALL	REAR AIRDAM						50.0
	INCTALL	PARKING SENSOR						60.0
E PNT98000	INSTALL	PARKING SENSOR						2260 0
	INT FOD D	REAR AIR DAM, REAR BU	IMDED DEAD	END DANE!				3360.0
		IP HOUSING RH LH, REA						
E PNT88000	THE CAN	" HOUSTING KIT EIT, KEF	IN LENDER I	7	pronj			200.0
	INSTALL	REAR COMPARTMENT TRI	MS d b F		45/=			200.00
M SUNDRY			911	Ima			İ	80.08
APPLY SEA	ALANT FOR	ACCIDENT PORTION T	S) [4]	(Q)		7	į.	00.0
M SUNDRY							ľ	20.00
Sundry								
A 90000001								30.00
	RING & EL	ECTRICAL SYSTEM						
A 10028901								120.00
		NOSTIC CHECK USING H	II-SCAN PRO	TEST				
USING HI-		. =						
M NEW K3 20		Y RED CR5			1.00	1721.00		1721.00
M COVER-RR M COVER-RR		un.			1.00	651.00		651.00
M COVER-RR					1.00	241.00		241.00
		OG LAMP,RH			1.00 1.00	33.00 88.00	100000000000000000000000000000000000000	33.00 88.00
M LAMP ASSY		-			1.00	181.00		181.00
M EXTN WIRI					1.00	207.00		207.00
M BRACKET-R					1.00		00.00	9.00
M BEAM-RR B		•			1.00	318.00		318.00
M BRACKET-R	R BEAM L	WR,CTR			1.00		00.00	6.00
M BRACKET-R	R BEAM L	WR MTG			1.00		00.00	6.00
M ANTENNA A	SSY-SMAR	TKEY			1.00	46.00	00.00	46.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
MR CHEONG	Cust No/Name	/PHILIP CHEONG SANG LEE		
	Reg No/Reg Date	SMF4546E / 13/11/201		
BLK 521 JELAPANG RD	Date In/Mileage	25/06/2021/ 0		
#05-161 SINGAPORE 670521	Chassis No	KNAF3416MK5019989		
SINGAPORE 070521	Engine No	G4FGJH709397		
Contact No 96231084	Make/Mode1	KIA/CERATO 1.6 A SR SX G335		
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00081	Cash	25/06/2021/ 11:39		442 / CocoLu		35217		
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
M STAY-RR E					1.00		00.00	65.0
		SPR SIDE UPR,R			1.00		00.00	31.0
		ASSY-BWS			1.00	163.00		163.0
M PANEL ASS M PANEL ASS		LID			1.00	1297.00		1297.0
M TRIM ASSY		ID			1.00	324.00		324.0
M W/STRIP-1					1.00 1.00	202.00 100.00		202.0 100.0
M LATCH ASS					1.00	112.00		112.0
M LOGO ASSY					1.00		00.00	32.0
M EMBLEM-CE					1.00		00.00	28.0
M TRIM ASSY		SVERSE			1.00		00.00	41.0
		MB OUTSIDE RH		ma	2 5.00	675.00		675.0
1 LAMP ASSY	-REAR CO	MB INSIDE, RH	≤ 1111	100121	1.00	608.00		608.0
M LAMP ASSY		GARNISH	9) [L] [1.00	690.00		690.0
1 ANTENNA A		TKEY			1.00	41.00		41.0
MUFFLER A	SSY-REAR				1.00	757.00	00.00	757.0
Confirm & ac	cepted by	,			7% GST on	Net 14643.0		14,643.0 1025.0
					Tot	al Payable	e	15,668.0
		and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.