

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

DATE : 25 JUN 2021

CLAIM TYPE : TP CLAIM

D.O.A : 18 JUN 2021

VEHICLE NO : GBK1532T

MAKE & MODEL : NISSAN/NV350 PANEL VAN 2.5 SAT

CHASSIS NO : JN1MC2E26Z0031499

TO : AIG

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	LIST PRICE	TOTAL PRICE
1	1	FRONT BUMPER	BR	\$ 571.90	\$ 571.90
2	1	FRONT BUMPER SIDE RETAINER RH	BR	\$ 147.00	\$ 147.00
3	1	FRONT FOG LAMP GARNISH RH	nn	\$ 104.70	\$ 104.70
4	1	HEADLAMP ASSY RH	CUT	\$ 672.00	\$ 672.00
5	1	FRONT STEP PANEL GARNISH RH	X	\$ 235.00	\$ 235.00
6	1	FRONT WHEEL HUB CAP LH	X	\$ 151.20	\$ 151.20
				\$ 1,881.80	\$ 1,881.80

TOTAL PRICE	\$ 1,881.80
DISCOUNT: 10%	\$ 188.18
SUB TOTAL PRICE	\$ 1,693.62

1390-90
- 10%
1251.81

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET	ACC	\$ 50.00	\$ 50.00
2	1	COMPANY REGISTRATION STICKER	X	\$ 30.00	\$ 30.00

TOTAL S/NETT	\$ 80.00	\$ 80.00
--------------	----------	----------

Labour Charges

1	To panel beat & straighten damaged panels. To remove & replace parts.	\$ 600.00	200
2	To apply anti rust coat and Tuff Kote affected areas	\$ 50.00	20
3	To check and rectify lighting & wiring harness	\$ 50.00	30
4	To Spray painting Front Bumper & front left door & affected parts	\$ 700.00	200

TOTAL LABOUR

Total Cost of Repairs

(Total parts + Total S/Nett + Total Labour Cost)

\$ 1,400.00
\$ 3,173.62

P- 1251.81
M- 30
L- 450
1731.81

Steve (LKK)
23/7/21

with AL
3 dy

P/P

M Bel sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: