

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8869Y

Make : HYUNDAI

Model : I-40

Date: 25/06/2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER BRACKET TOP LH			\$44.80
1	FRT FENDER LH			\$663.00
1	HEADLAMP LH			\$1,800.00
	SUB TOTAL			\$3,582.00
	LESS 20%			\$716.40
	DISCOUNTED TOTAL			\$2,865.60
	FRT FENDER ADVERTISEMENT LOGO LH			\$100.00
				Nett
				\$100.00
				Nett
	Labour Charge			
	PANEL BEATING			\$600.00
	SPRAY PAINTING CHARGE			\$600.00
	WIRING CHARGE			\$60.00
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL			\$4,225.60

DEF
NEC
KR
SCR

Nett
NEC

\$850
500
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

N/A2 LKK
25/6/2021 1705
LIS
3 Days
CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: