



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105001

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/07/2021
Reference CC4/FCI21007032/Ura3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 4067S
Insured Veh. YN 2956J
Claim No. D21001887MFCV/2
Policy No. D-21097378MFCV
Accident Date 23/06/2021
Inspection Date 25/06/2021

Description	Total
Survey Inspection	496.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	496.00
GST (7%)	34.72
Grand Total	530.72

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21007032/Ura3q2	
			Date: 15/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 2956J	Veh. Inspected	GBC 4067S
	Policy No.	D-21097378MFCV	Coverage (\$)	0.00
	Claim No.	D21001887MFCV/2	Excess (\$)	0.00
	Assign From	KAREN TAN	Assign Date	25/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 (M)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	VSKYBAM20U0033552	Colour	GREY
	Odometer	356863 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	FALKEN	6 mm
	L/H Front Tyre	175/70 R14	FALKEN	6 mm
	R/H Rear Tyre	175/70 R14	FALKEN	6 mm
	L/H Rear Tyre	175/70 R14	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/06/2021	Inspection Date	25/06/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 4067S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BACK DOOR N/S	BADLY DENTED	1,610.10	1,336.00
1	REAR BACK DOOR 'NV 200' EMBLEM N/S	NECESSARY	205.30	141.70
1	REAR BACK DOOR REAR LOGO N/S	NECESSARY	66.80	66.80
1	REAR BACK DOOR OUTER HANDLE N/S	GRAZED	168.50	168.50
1	REAR BACK DOOR LOWER N/S	SHORTED / JAMMED	299.30	135.20
1	REAR BACK DOOR INNER TRIM N/S	TORN	625.10	241.20
1	SET REAR BACK DOOR INNER TRIM CLIPS N/S	NECESSARY	25.00	25.00
1	REAR WIPER MOTOR	BENT / JAMMED	845.20	650.00
1	REAR WIPER ARM	SERVICEABLE	95.00	-
1	REAR BACK DOOR O/S	DENTED	1,615.10	910.90
1	REAR BACK DOOR 'DCI' EMBLEM O/S	NECESSARY	66.80	66.80
1	REAR BACK DOOR LOWER LOCK O/S	SERVICEABLE	299.30	-
1	REAR BACK DOOR INNER RUBBER O/S	TWISTED	288.50	165.30
1	REAR BACK DOOR INNER TRIM O/S	NOT NECESSARY	605.10	-
1	SET REAR BACK DOOR INNER TRIM CLIPS O/S	NOT NECESSARY	30.00	-
1	REAR BUMPER	DEFORMED	822.30	485.90
2	REAR BUMPER REFLECTORS @\$60.00	NOT NECESSARY	120.00	-
1	REAR BUMPER SPONGE	TORN	288.00	194.20
2	REAR BUMPER SIDE HOLDERS @\$95.00	NOT NECESSARY	190.00	-
2	TAILLAMPS @\$480.00	N/S CRACKED	960.00	252.10
1	REAR END PANEL	DENTED / BENT	655.20	288.20
1	REAR END PANEL TOP GARNISH	TWISTED	311.30	80.60
1	REAR END PANEL WEATHERSTRIP	TWISTED	366.50	245.30
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,420.00	-
	LESS 10% DISCOUNT		-	-545.37
			11,978.40	4,908.33
<u>SPECIAL NETT ITEMS</u>				
1	REAR BACK DOOR GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	70KM/H STICKER (SN)	NECESSARY	20.00	10.00

Report Ref No. CC4/FCI21007032/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BACK DOOR GLASS SEALANT O/S (SN)	NECESSARY	50.00	40.00
1	6 PAX STICKER (SN)	NECESSARY	20.00	10.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
			630.00	330.00
	LABOUR			
	TO CHECK WIRING .		80.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX BOTH BACK DOOR GLASS .		300.00	200.00
	TO DISMANTLE & REFIX BOTH BACK DOOR MECHANISM.		200.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	80.00	-
	TO SPRAY RUST PROOFING .		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	700.00
			3,860.00	1,770.00
GRAND TOTAL			16,468.40	7,008.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,600.00

Report Ref No. CC4/FCI21007032/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 4067S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 4067S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 4067S

RE-INSPECTION

