

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBK 5144D

Vehicle Model : TOYOTA HIACE

Accident Date : 24.06.2021

Original Reg Date : 25.08.2020

Date : 25.06.2021

Chassis : JTFHT02PX09990145

TP Ins. **ERGO**

ESTIMATE

1	1 pc	Tailgate		bt / 1,969.30	1855
2	1 pc	Tailgate Badge		ne / 62.00	
3	1 pc	Tailgate Sticker TOYOTA HIACE		ne / 56.00	
4	1 pc	Tailgate Windscreen Inner Seal		ne / 50.00	
5	1 pc	Tailgate Inner Lock		? bt / 461.60	260
6	1 pc	Tailgate Auto Lock Actuator		? bt / 456.20	289.70.
7	1 pc	Tailgate Lock Mechanism		? bt / 235.10	
8	1 pc	Tailgate Lock Catch		X nn / 42.00	
9	1 pc	Tailgate Weatherstrip		? wt / 381.90	288-60.
10	2 pcs	Tailgate Side Stopper (Male)	36.00	X nn / 72.00	
11	2 pcs	Tailgate Side Stopper (Female)	39.00	X nn / 78.00	
12	1 pc	Tailgate Inner Trim Board		X nn / 235.60	
13	1 set	Tailgate Inner Trim Board Clips		X nn / 40.00	
14	2 pcs	Tailgate Hinges	85.90	X nn / 171.80	
15	2 pcs	Tailgate Absorber	389.60	X nn / 779.20	
16	1 pc	Taillamp LH		cn / 297.20	
17	1 pc	Taillamp Bottom Corner Garnish LH - photo.		de / 96.00	
18	1 pc	Taillamp Bottom Corner Garnish Retainers LH - photo		ne / 38.00	
19	1 pc	Rear Bumper		de / 495.60	
20	2 pcs	Rear Bumper Side Retainers	69.20	- 138.40	69.20.
21	1 set	Rear Bumper Clips	30.	ne / 50.00	30
22	4 pcs	Rear Bumper Stay	18.00	? dis / 72.00	
23	1 pc	End Panel (Inner)		bt / 994.80	807.50
24	1 pc	End Panel (Outer)		bt / 492.50	349.80
25	1 pc	End Panel Top Plate		bt / 192.00	
26	2 pcs	Rear Air Vents	52.00	de / 104.00	
27	1 pc	Spare Tyre Carrier		bt / 223.60	
28	1 pc	Spare Tyre Carrier Bolt		X nn / 58.20	
29	1 pc	Spare Tyre Carrier Nut		X nn / 69.50	
				8,412.50	5871.30
Less 25%				2,103.13	4403.48
				6,309.38	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBK 5144D

B/F

6,309.38

Special Nett

1	1 pc	Tailgate Sticker 70km/h		15.00
2	1 pc	Rear Windscreen Sealant		60.00
3	1 set	Body Panel Joint Sealant	nec	120.00
4	1 set	Reverse Sensor	nec	250.00

335

Labour charge

Panel Beating	800	1,300.00
Spray painting	900	1,200.00
Check Wiring	30	50.00
Anti rust	30	90.00
Remove and install rear winscreen.	120	140.00
Remove and install tailgate parts.	60	90.00
Remove and install carpet and interior	80	250.00
Remove and install reverse sensor.	30	90.00
Remove and install reverse camera.	30	120.00

2080

10,084.38

Less 20% 2,016.88

Lump sum 8,067.50

Tan Kah 97415149
WP 25/6/71 @ 320

1/6 Repair after repair

6 days

Tan Kah @ lkkauto.com

4403.48

335

2080

6818.48

45450 #

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: