

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SL52228C*
at Workshop m/s: *PA 46, 2nd.*
of _____
Insured: *PC 3202J*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *£55k.*
IDAC Accident Rpt: _____ Consistent?: Yes or No
GA / PR Seen: *✓* Consistent?: Yes or No
Est. Repairs: *4* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

356D
Vehicle: IN / OUT

Date / Time _____ Action / Instruction _____

*have video footage at work
P1 door - 1542 rubber 122 mirror 498 Rear door 1361
resumy 9-7-21*

23/3/21 L/S & 3550 confirmed with Ray

Veh No: *SL52228C* Yr Regn: *14/9/17*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CAI*
Make: *KIA ceato k3* c.c. *1591*
Colour: *Green* A/C: *Insured / Std / NI / NA*
Sp. Reading: *58412* T/Radio: *Insured / Std / NI / NA*
Eng/No: _____
C/No: *KNAFX411M95741386*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *order* / Jammed / Leaked / Burnt or
Brake: *order* / Jammed / Leaked / Burnt or
Modi: *NI / S/Rim / STD A/Rim or*
Tyre Size: *F: 205/55-R16*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *maxon*
Front: *6* Rear: *6*
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. *0* mm L/Bal. *6* mm
D.O.A. *21/6/21* D.O.I. *29/6/21*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
n/s frt, n/s body
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prefi. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

Not Attached
4 days L/S # 3830
29/6/21
The file is the
copy

M/S: TAN THYE LYE
BLK 642D PUNGOL DRIVE #18-375
SINGAPORE 824642

Estimate No: EST1507049
Date: 21 Jun 2021
Policy No: PNPV2020-00008896
Veh Reg No: SLS2229C
Make/Model: KIA CERATO K3 1.6A
Chassis No: KNAFX411MJ5741386
Engine No: G4FGHH678879
Reg. Date: 14/09/2017

ATTN: CHINA TAIPING
Your Ref No: TP 0621-6411
Claim Type: Third Party
Accident Date: 21/06/2021
TP Veh Reg No: PC 3202 J

Estimate Repair Cost to Vehicle No :SLS2229C

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 FRONT BUMPER R	633.00	1 PC	633.00 X	
2 FRONT BUMPER CLIPS 11	5.00	10 PC	50.00 X	
3 FRONT FENDER - LH R	342.00	1 PC	342.00 X	
4 FRONT FENDER COWLING CLIPS - LH 11	5.00	10 PC	50.00 X	
5 FRONT DOOR - LH DD	1,279.00	1 PC	1,279.00	
6 FRONT DOOR RUBBER - LH 11	110.00	1 PC	110.00	
7 FRONT DOOR STICKER - LH 11	30.00	1 SET	30.00	
8 FRONT DOOR RUBBER - LH Repack	110.00	1 PC	110.00 X	
9 FRONT DOOR REGULATOR GEAR - LH 11	293.00	1 PC	293.00 X	
10 FRONT DOOR REGULATOR GEAR MOTOR - LH 11	326.00	1 PC	326.00 X	
11 FRONT DOOR LOCK - LH 11	228.00	1 PC	228.00 X	
12 FRONT DOOR OUTER CHANNEL MOULDING - LH 11	102.00	1 PC	102.00 X	
13 FRONT DOOR OUTER HANDLE, BIG - LH 11	52.00	1 PC	52.00	
14 FRONT DOOR OUTER HANDLE, SMALL - LH 11	20.00	1 PC	20.00	
15 REAR DOOR - LH DD	1,184.00	1 PC	1,184.00	
16 REAR DOOR RUBBER - LH 11	103.00	1 PC	103.00	
17 REAR DOOR STICKER - LH 11	25.00	1 SET	25.00	
18 REAR DOOR RUBBER - LH Repack	103.00	1 PC	103.00 X	
19 REAR DOOR OUTER CHANNEL MOULDING - LH 11	139.00	1 PC	139.00 X	
20 REAR FENDER CORNER STICKER - LH 11	24.00	1 PC	24.00 X	
21 SIDE MIRROR ASSY - LH R	449.00	1 PC	449.00 X	
22 SIDE MIRROR OUTER COVER - LH 11	161.00	1 PC	161.00 X	
23 REAR RIM KIA, SMALL - LOGO 11	25.00	1 PC	25.00 X	
			5,838.00	
	Less 10%		583.80	5,254.20
Special Net				
24 REAR RIM - LH 11	800.00	1 PC	800.00 X	
			800.00	800.00
Labour				
25 TO KNOCK OUT DENTS, LH REAR FENDER, CENTRE DOOR PILLAR - LH, REMOVE, REPLACE ACCIDENT PARTS	1,000.00	1 JOB	1,000.00 600	
26 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.00	1 JOB	1,200.00 800	
27 TO TUFF-KOTE	100.00	1 JOB	100.00 60	
28 TO CHECK WIRING	50.00	1 JOB	50.00	
29 TO TRANSFER DOOR AND DOOR FITTING	160.00	1 JOB	160.00 120	
30 TO 4 WHEEL ALIGNMENT	75.00	1 JOB	75.00 X	
31 TO REMOVE, REPLACE LH REAR RIM, TYRE BALANCING	50.00	1 JOB	50.00 X	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: TAN THYE LYE
BLK 642D PUNGGOL DRIVE #18-375
SINGAPORE 824642

ATTN: CHINA TAIPING
Your Ref No: TP 0621-6411
Claim Type: Third Party
Accident Date: 21/06/2021
TP Veh Reg No: PC 3202 J

Estimate No: EST1507049
Date: 21 Jun 2021
Policy No: PNPV2020-00008896
Veh Reg No: SLS2229C
Make/Model: KIA CERATO K3 1.6A
Chassis No: KNAFX411MJ5741386
Engine No: G4FGHH678879
Reg. Date: 14/09/2017

Estimate Repair Cost to Vehicle No :SLS2229C

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
32 TO RESET CHECK LIGHT	100.00	1 1 JOB	100.00	
			2,735.00	2,735.00
Total				S\$ 8,789.20
Add GST @ 7%				615.24
Total Amount Payable				S\$ 9,404.44

TOTAL: SINGAPORE DOLLAR NINE THOUSAND FOUR HUNDRED AND FOUR CENTS FORTY FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-2803
102
28227

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

TEL: 63896111 FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your RefNo: TP 0621-6411

Claim Type: Third Party

Accident Date: 21/06/2021

TP Veh Reg No: PC 3202 J

Estimate No: EST1507049

Date: 09 Jul 2021

Policy No: PNPV2020-00008896

Veh Reg No: SLS2229C

Make/Model: KIA CERATO K3 1.6A

Chassis No: KNAFX411MJ5741386

Engine No: G4FGHH678879

Reg. Date: 14/09/2017

Estimate Repair Cost to Vehicle No :SLS2229C

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Special Net				
1 DOOR INSULATOR - LH		1set 1PC	180.00	✓
2 DOOR STICKER - LH		1set 1PC	150.00	✓
			330.00	330.00
Total			S\$ 330.00	
GST Amount			S\$ 23.10	
Total Amount Payable			S\$ 353.10	

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 330.00

PAID 252.70

LAB 160.00

448.70

1/2 = 355.00