



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 25.06.2021
Emailed : 16.07.2021, 4.20pm
Date Survey : 28.06.2021

VEHICLE NO : SMX 9695 E
MODEL : KIA CERATO 1.6 A GT
WIP : 35297

Material	:	\$	<u>6,240.80</u>
Labour	:	\$	<u>5,800.00</u>
Sub-Total	:	\$	<u>12,040.80</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>11,740.80</u>
GST 7%	:	\$	<u>821.86</u>
Grand Total	:	\$	<u>12,562.66</u>
Finalise By/Date	:	<u>LOI / 16/07/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 29/06/2021	Cust No/Name	LCV13858/CHONG KIA KEONG
	Reg No/Reg Date	SMX9695E / 08/02/2021
	Date In/Mileage	29/06/2021/ 2452
	Chassis/Package	KNAF5416MM5097459 /#
	Engine No	G4FGKH741487
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	16/07/2021/ 15:03	BLE	260 / AiTing	35297			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, REPAIR RH FRONT DOOR, RH FRONT A PILLAR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								1920.00
E PNT98000								30.00
RESPRAY ON FRONT BUMPER, RH FRONT FENDER, RH FRONT A PILLAR, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								120.00
A 54900099								120.00
CHECK WIRING & ELECTRICAL SYSTEM								400.00
A 10028901								40.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								20.00
A WHEELALIGNMENTBP								400.00
CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								40.00
A 33900099								400.00
REPLACE RH FRONT UNDERCARRIAGE PARTS								40.00
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								20.00
M SUNDRY								400.00
SUPPLY BODY PANEL SEALANT								400.00
M SUNDRY								1440.00
SUNDRIES								30.00
E PNT88000								-300.00
REPLACE FRONT SUPPORT PANEL → Supp.								506.40
E PNT88000								172.80
REPAIR & REPLACE RH FRONT WHEEL HOUSE PANEL → Supp.								
E PNT98000								
RESPRAY BONNET, RH SIDE SILL & RH WHEEL HOUSE PANEL → Supp.								
S SPECIALISTJOB								
REPLACE RH FRONT SPORTS RIM								
X EXC								
EXCESS								
X COVER-FR BUMPER					1.00	633.00	20.00	
X MOULDING-FRONT BUMPER,RH					1.00	216.00	20.00	



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13858/CHONG KIA KEONG Reg No/Reg Date SMX9695E / 08/02/2021 Date In/Mileage 29/06/2021/ 2452 Chassis/Package KNAF5416MM5097459 /# Engine No G4FGKH741487 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK
29/06/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/07/2021/ 15:03	BLE	260 / AiTing	35297

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LAMP ASSY-SIDE REPEATER,RH	1.00	✓ 143.00	20.00	114.40
X LAMP ASSY-HEAD,RH	1.00	✓ 2210.00	20.00	1768.00
X PANEL-FENDER,RH	1.00	✓ 430.00	20.00	344.00
X GUARD ASSY-FRONT WHEEL,RH	1.00	✓ 95.00	20.00	76.00
X MOULDING ASSY-SIDE SILL,RH	1.00	? 279.00	20.00	223.20
X ORNAMENT-KIA NO.115	1.00	? 32.00	20.00	25.60
X CARRIER ASSY-FRONT END MODULE	1.00	? 675.00	20.00	540.00
X CROSSMEMBER COMPL	1.00	? 1156.00	20.00	924.80
X ARM COMPLETE-FR LWR,RH	1.00	✓ 286.00	20.00	228.80
X WHEEL ASSY-ALUMINIUM	1.00	✓ 926.00	20.00	740.80
X CLIP	15.00	✓ 1.00	20.00	12.00
X INSULATOR-FENDER RH	1.00	27.00	20.00	21.60
X GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00
X RESERVOIR & PUMP ASSY-WASHER	1.00	146.00	20.00	116.80
X BRACKET-FR BUMPER UPR SIDE MTG	1.00	? 22.00	20.00	17.60
X CAP ASSY-WHEEL HUB	1.00	25.00	20.00	20.00
Z TEXT				
AIG OD CLAIM				
DOA : 25.06.21				
SURVEYOR STEVE LKK 28.06.21				
POLICY NO : 7210013651 REPAIR 07 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	6,240.80	Nett	11,740.80
Labour	5,630.00	7% GST on	11740.80
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	12,562.66
Diagnostics Job	0.00		
Sundry/Others	-160.00		
Total(w/o GST)	11,740.80		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMX 9695 E**

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (x15)	15.00 / REC
2	Insulator-fender RH	27.00 / CRU
3	Grille-front bumper	485.00 / CUT
4	Reservoir & pump assy-washer	146.00 / CRU
5	Cap assy-wheel hub	25.00 / CUT
Total Materials		698.00
Less 20% discount		139.60
Total after discount		558.40
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front support panel	400.00 /
2	Repair & replace RH front wheel house panel	400.00 /
3	Respray bonnet, Rh side sill, & RH wheel house panel	1,440.00 /
Total labour		2,240.00
Total amount		2,798.40
7% GST		195.89
Grand total		\$ 2,994.29

Thank You.
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	FRT SUPPORT PNL	? / SUPP		BR	
2	RAH WHEELHOUSE (INNER) SUPPORT	? / SUPP		DD (Small)	
3	RAH FENDER TRIM	? / SUPP		CR4	
4	RAH ROCKER PNL SIDE SILL	? / SUPP		BR	
5	RAH BUMPER LOWER	? / SUPP		CR4	
6	RAH BUMPER LOWER GRILLAS	? / SUPP		NC	
7	RAH BUMPER GRIPS (15 X)	? / SUPP		BR NC	
8	RAH FENDER BRACKET	? / SUPP		BR	
9		? / SUPP			
10	REPAIR & REPLACE RAH WHEELHOUSE PNL	? / SUPP	\$ 400		Start
11	RENEW FRT SUPPORT PNL - \$ 400	? / SUPP			29/6/21
12	REPAIR & REPLACE	? / SUPP			
13	RESTRAY BONNET \$ 480	? / SUPP			
14	SIDE SILL RH \$ 480	? / SUPP			CR5 \$480 per panel
15	WHEELHOUSE PNL \$ 480	? / SUPP			Quoted Red
16		? / SUPP			
17	ADDITIONAL WORKING DAYS 2	? / SUPP			
18		? / SUPP			
19	WASHER TANK	? / SUPP		CR4	Start 1/7/21
20	WHEEL CAP - VDO 141	? / SUPP		CR1	

DATE	TAKEN BY

MODEL: CERATO

SURVEYOR: STEVE

CAR NO: SNIX 91695F

WIP: (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RHF KNUCKLE ARM	? / SUPP			
2	RHF KNUCKLE PEARING	? / SUPP			
3	RHF SHOCK ABSORBER	? / SUPP			
4	Suspension cross member fl	? / SUPP		- B7	Stuck 12/7/21
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: _____

SURVEYOR: _____

Work Order: R001481
 License: smx 9695 e
 Technician: 810119 kfsan
 Mileage: 2454
 Date: 12.7.21 16:41

AFH

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-0°20'	-0°20'	-0°53' 0°07'
4°17'	4°17'	4°00' 5°00'
0°02'	0°02'	-0°03' 0°09'
11°29'*	11°29'*	13°30' 14°30'
11°09'*	11°09'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°46'	-0°46'	-0°53' 0°07'
4°59'	4°59'	4°00' 5°00'
-0°02'	-0°02'	-0°03' 0°09'
12°03'*	12°03'*	13°30' 14°30'
11°17'*	11°17'*	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°26'	0°26'	
-0°42'	-0°42'	
-0°34'	-0°34'	
0°00'	0°00'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°05'	-1°05'	-1°42' -0°42'
0°01'	0°01'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°25'	-1°25'	-1°42' -0°42'
0°13'	0°12'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°20'	0°20'	
0°13'	0°13'	-0°04' 0°32'
-0°06'	-0°06'	


* This value is not within specification. Tire wear, handling and safety prob.



Fault Code Searching

Rescan

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0249

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0190

OS Ver.

Android 10