



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13858/CHONG KIA KEONG Reg No/Reg Date SMX9695E / 08/02/202 Date In/Mileage / 0 Chassis No KNAF5416MM5097459 Engine No G4FGKH741487 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	26/06/2021/ 08:44	BLE	261 / Edwin Caina	35297			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2400.00
RENEW FRT BUMPER , RHF FENDER , FRT SUPPORT & RH ROCKER SIDE SILL PNL								
REPAIR RHF DOOR , RHF A PILLAR & BONNET								
E PNT98000								2100.00
RESPRAY FRT BUMPER , BONNET , RHF FENDER , RHF A PILLAR , RHF DOOR &								
RH ROCKER PNL SIDE SILL								
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								80.00
TOP UP AC GAS								
M SUNDRY								30.00
TO RENEW RHF SPORT RIM & TYRE								
M SUNDRY								380.00
SUPPLY RHF TYRE								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
A 33900099								800.00
RENEW FRT U/CARRIAGE RH								
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								80.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundries								
M	COVER-FR BUMPER				1.00	633.00	20.00	506.40
M	GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M	MOULDING-FRONT BUMPER,RH				1.00	216.00	20.00	172.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13858/CHONG KIA KEONG Reg No/Reg Date SMX9695E / 08/02/202 Date In/Mileage / 0 Chassis No KNAF5416MM5097459 Engine No G4FGKH741487 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	26/06/2021/ 08:44	BLE	261 / Edwin Caina	35297

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE REPEATER,RH	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,RH	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00
M PANEL-FENDER,RH	1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL,RH	1.00	95.00	20.00	76.00
M MOULDING ASSY-SIDE SILL,RH	1.00	279.00	20.00	223.20
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
M GEAR ASSY-STEERING	1.00	770.00	20.00	616.00
M KNUCKLE-FRONT AXLE,RH	1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80
M BAR ASSY-FR STABILIZER	1.00	238.00	20.00	190.40
M LINK-STABILIZER	1.00	72.00	20.00	57.60
M STRUT ASSY-FR,RH	1.00	280.00	20.00	224.00
M BEARING-STRUT	1.00	86.00	20.00	68.80
M BEAM COMPLETE-FR BUMPER	1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00
M CROSSMEMBER COMPL	1.00	1156.00	20.00	924.80
M ARM COMPLETE-FR LWR,RH	1.00	286.00	20.00	228.80
M STAY RH	1.00	22.00	20.00	17.60
M WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80

SURVEYOR NAME : \_\_\_\_\_

SURVEYOR SIGNATURE : \_\_\_\_\_

DATE : \_\_\_\_\_

REMARKS : \_\_\_\_\_

Confirm & accepted by \_\_\_\_\_

<b>Nett</b>	<b>14,776.00</b>
<b>7% GST on</b>	<b>14776.00</b>
<b>Total Payable</b>	<b>15,810.32</b>

Authorized signatory and company stamp \_\_\_\_\_

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.