

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0537/2021/TF
DATE : 6-May-21
WIP : 25767

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 30/06/2021

YOUR INSURED VEH NO : SKB 2542 Z

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. YIP YIMING SHAUN
ADDRESS : 361 BUKIT TIMAH ROAD
#12-06
SINGAPORE 259725
TELEPHONE : HP +65 91856233
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800152789-01
VEHICLE NO : **SJY 9080 J**
MODEL CODE : A4 SEDAN 2.0 TFSI
MODEL YEAR : 21/12/2018
ENGINE NO : CVK 071504
CHASSIS NO : WAUZZZF43KN000623
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jun-21
PLACE OF ACCIDENT : DUNEARN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 9080 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE & REINSTALL REAR PARKING AID.	S/N \$ 360.00	✓
2	TO DISMANTLE RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	500
3	TO RESPRARY REAR BUMPER AND LHS REAR FENDER	\$ 2,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK ✓	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,952.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 9080 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Rehman d</i>	1	\$ 2,996.00	✓	
2	REAR BUMPER FIXING PARTS <i>Rehman</i>	1	\$ 459.00	✗	
3	REAR BUMPER SPOILER <i>cut</i>	1	\$ 249.00	✓	
4	REAR BUMPER TRIM <i>Rehman</i>	1	\$ 292.00	✗	
5	REAR BUMPER BRACKET - LH <i>Rehman</i>	1	\$ 116.00	✗	
6	REAR BUMPER SECURING STRIP <i>?</i>	1	\$ 223.00	?	
7	REAR LIGHT REFLECTOR - LH <i>Rehman</i>	1	\$ 41.00	✗	
8	REAR TAIL LIGHT - LH OUTER <i>Rehman</i>	1	\$ 1,019.00	✗	
9	REAR TRIM TAIL LIGHT - LH OUTER <i>Rehman</i>	1	\$ 30.00	✗	
10	REAR BUMPER CARRIER <i>Rehman</i>	1	\$ 1,063.00	✗	
11	REAR BUMPER SEAL <i>Rehman</i>	2	\$ 28.00	✗	
12	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 44.00	?	
13	REAR BUMPER UPPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 46.00	?	
14	REAR BUMPER HOLDING STRIP - LH / RH <i>Rehman</i>	2	\$ 166.00	✗	
15	AERIAL BRACKET <i>Rehman</i>	1	\$ 26.00	✗	
16	AERIAL	1	\$ 174.00	✗	
17	REAR PARKING AID SENSOR <i>Rehman</i>	2	TBC		
18	REAR BUMPER PARKING AID SENSOR SEAL <i>Rehman</i>	4	\$ 14.00	✗	
19	BOOT LID CONTROL UNIT <i>Rehman</i>	1	\$ 411.00	✗	
20	EXHAUST TAIL PIPE TRIM - LH <i>Rehman</i>	1	\$ 354.00	✗	
21	SUNDRIES <i>?</i>	S/N	\$ 250.00	?	
TOTAL SPARE PARTS		:	\$ 8,001.00		
TOTAL LABOUR CHARGES		:	\$ 3,952.00		
GRAND TOTAL		:	\$ 11,953.00		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *20/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT