

Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Lawrence Yong Tet Min
539 Hougang Street 52, #08-64 Singapore 530539

Contact : 97358443

ESTIMATE

Code : C102003

Date in : 01/07/2021


Vehicle Num. : SGS7676X

Model : HONDA CITY 1.5 SV CVT

Chassis/Eng# : MRHGM6660HP000568/L15Z14116763

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Front Bumper	1	459.80 597.74	597.74
Front Bumper Foglamp Garnish LH	1	35.36	35.36
Front Bumper Foglamp LH	1	319.60	319.60
Front Bumper Reinforcement Beam	1	277.50	277.50
Front Bumper Side Holder LH	1	21.80	21.80
Front Fender Inner Cowling LH	1	125.19	125.19
Front Fender LH	1	378.20	378.20
Front Headlamp Assy LH	1	345.80	345.80
Front Headlamp Retainer LH	1	35.75	35.75
Subtotal before discount		863.15	2,136.94
Percentage discount 20%		690.52	427.39
Sub-total 1			1,709.55
Front Bumper Clips (Set) (SN)	1	50.00	50.00
Front Fender Inner Cowling Clips (SET) (SN)	1	50.00	50.00
Subtotal before discount		100	100.00
Percentage discount 0%			0.00
Sub-total 2			100.00
Parts-total			1,809.55



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE * PERFORMANCE

Company Registration No. 201118055N

LABOUR

Description	Price
To provide labour to send vehicle for off peak number plate and LTA sealing charges	60. 120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30. 100.00
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	nn x 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	400 800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	400. 700.00
OPC Coupon (20x2)	✓ 40.00
Labour Total	930 1,860.00
Parts & Labour Total	3,669.55

page 2

Tanpin 9749549 690.52
 WP' 1/2/21 @ 330pm 30
 930
 1/3 Resurvey after repair ✓ 1650.52
 03 days 4/5 \$1300
 Tanpin @ 1/2/21 03 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: