Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 29 Jun 2021 Jenny Lew Date:

Preliminary Advice

Insured Vehicle No : PC1393D

TP Vehicle No : SFS735S : 25/06/2021 Accident Date Make : MERCEDES-BENZ 220E **Assignment Date** : 28/06/2021

Date of Inspection : 29/06/2021

Inspection At : CONNECT3 (HQ)

566 WOODLANDS ROAD SINGAPORE 728697

Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,785.00
Revised Amount	:S\$	5,235.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,235.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS (X) AVAILABLE.