

Date: 25.06.2021

Vehicle No: SMX8248U

Model: TOYOTA NOAH HYBRID 1.8X CVT

Chassis: ZWR800452231-2020

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SKV1983K

Date of Accident: 24.06.2021

Estimator: TING AN

Surveyor:

*Not Notified
Per survey B4 pain
4-5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bu</i> \$1,812.00 ✓
2	REAR TAILGATE "HYBRID" EMBLEM	1		<i>me</i> \$50.00 ✓
3	REAR TAILGATE INNER LOCK	1		<i>R</i> \$467.00 X
4	REAR TAILGATE INNER TRIM BOARD	1		<i>SL</i> \$570.00 X
5	REAR TAILGATE RUBBER	1		\$372.00 7
6	REAR WINDSCREEN MOULDING	1		<i>me</i> \$120.00 ✓
7	REAR BUMPER	1		<i>Bu</i> \$545.00 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>SL</i> \$74.00 X
9	REAR BUMPER SIDE BRACKET RH	1		<i>me</i> \$74.00 X
10	REAR BUMPER TOWING COVER	1		<i>SL</i> \$25.00 X
11	REAR END PANEL	1		\$435.00 7
12	REAR END PANEL UPPER COVERING	1		\$162.00 7
13	REAR FLOOR PANEL	1		<i>R</i> \$698.00 X
14	REAR FLOOR PANEL TRAY BOX	1		<i>SL</i> \$489.00 X
15	REAR FLOOR PANEL TRAY UPPER BOARD	1		<i>me</i> \$905.00 X
SUB TOTAL				\$6,798.00
LESS 25%				-\$1,699.50
PARTS TOTAL				\$5,098.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>me</i> \$40.00 X
2	REAR WINDSCREEN SEALANT	1		<i>me</i> \$80.00 405me
3	REAR BUMPER REVERSE SENSOR	1		<i>me</i> \$300.00 2001me
4	REAR END PANEL UPPER COVERING CLIPS	1		<i>me</i> \$30.00 ✓
5	REAR END PANEL JOINT SEALANT	1		\$40.00 7
S/N TOTAL				\$490.00

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 25.06.2021
Vehicle No: SMX8248U
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800452231-2020
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SKV1983K
Date of Accident: 24.06.2021
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	\$900.00	7
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL & ETC.	\$900.00	600/
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.	\$150.00	120/
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	50/
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	7
TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.	\$80.00	20/
LABOUR TOTAL	\$2,400.00	

TING AN	TOTAL	\$7,988.50
---------	--------------	-------------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

