

ESTIMATE

Company Reg No. 200809327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
GOH CHYAN YEE 2 BISHAN STREET 25 #09-03 SINGAPORE 573973 Contact No Mobile: 96676278	Cust No/Name /GOH CHYAN YEE Reg No/Reg Date SJP5420K / 27/12/2018 Date In/Mileage / 0 Chassis No VF73AHNYTJJ793471 Engine No 10XTA41173070 Make/Model CIT/GRAND C4 SPACETOURER 1.2 PURETECH 13 Colour/Trim EBM LAZULI BLUE / 8LP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	28/06/2021/ 12:36	BLC	442 / CocoLu	16670

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET, FRT BUMPER, FRT AIRDAM, FRT FENDER LH, FRT SUPPORT PANEL REPAIR FRT DOOR LH,	570 X 2-5			1250 2500.00
E PNT88000 REMOVE & INSTALL FRT AIRDAM				100.00
E PNT98000 SPRAY PAINT FOR FRT AIRDAM, FRT FENDER LH, FRT BUMPER, BONNET FRT SUPPORT, FRT DOOR LH,	380 X 5			1900 3120.00
A 54900099 CHECL WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				225.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
M FRONT BUMPER	1.00	1031.00	0.00	1031.00
M BUMPER BRACKET	1.00	330.00	0.00	330.00
M BUMPER MOULDING	1.00	207.00	0.00	207.00
M BUMPER MOULDING	1.00	227.00	0.00	227.00
M BMR RUBBR BOOT	1.00	276.00	0.00	276.00
M GUARD GRILLE INFERIEUR	1.00	311.00	0.00	311.00
M BADGE SUPPORT	1.00	205.00	0.00	205.00
M CHEVRON EMBLEM SUPERIEUR	1.00	161.00	0.00	161.00
M CHEVRON EMBLEM INFERIEUR	1.00	161.00	0.00	161.00
M BRACKET SET	1.00	125.00	0.00	125.00
M BUMPER MOULDING	1.00	173.00	0.00	173.00
M BRACKET SET LAT	1.00	125.00	0.00	125.00
M ABSORBERS SET	1.00	92.00	0.00	92.00
M BUMPER BRACKET	1.00	516.00	0.00	516.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR 8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
GOH CHYAN YEE		Cust No/Name	/GOH CHYAN YEE
2 BISHAN STREET 25		Reg No/Reg Date	SJP5420K / 27/12/2018
#09-03		Date In/Mileage	/ 0
SINGAPORE 573973		Chassis No	VF73AHNYTJJ793471
Contact No Mobile: 96676278		Engine No	10XTA41173070
		Make/Model	CIT/GRAND C4 SPACETOURER 1.2 PURETECH 13
		Colour/Trim	EBM LAZULI BLUE / 8LP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	28/06/2021/ 12:36	BLC	442 / CocoLu	16670			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PLUG LH	1.00	96.00	0.00	96.00			
M	FACE CROSSMEMBR SUP	1.00	226.00	0.00	226.00			
M	AIR BULKHEAD LH	1.00	108.00	0.00	108.00			
M	AIR BULKHEAD	1.00	154.00	0.00	154.00			
M	BRACKET CROSSME LH ASS	1.00	196.00	0.00	196.00			
M	FACING SUPPORT LH ASS	1.00	90.00	0.00	90.00			
M	FRONT WING LH ASS	1.00	571.00	0.00	571.00			
M	MUDGUARD LH ASS	1.00	194.00	0.00	194.00			
M	ENGINE BONNET ASS	1.00	1042.00	0.00	1042.00			
M	BONNET HINGE LH	1.00	178.00	0.00	178.00			
M	FRONT LIGHT LH	1.00	409.00	0.00	409.00			
M	HEADLIGHT ASSY LH	1.00	718.00	0.00	718.00			
M	SPACETOURER 2018 - BODY KIT	1.00	1500.00	0.00	1500.00			

Estimate

Steve (LKK) 00-11 AL
 28/6/21, 2.0pm EXPRESS-?
 PIP

M B L G
 6 djs

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer
 Signature:
 Date:

Parts	9,422.00
Labour	5,975.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	110.00
Sundry/Others	15,507.00
Total(w/o GST)	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.