

ESTIMATE

Company Reg No. 200509327M
 GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info				
GOH CHYAN YEE				Cust No/Name	/GOH CHYAN YEE			
2 BISHAN STREET 25				Reg No/Reg Date	SJP5420K / 27/12/2018			
#09-03				Date In/Mileage	/ 0			
SINGAPORE 573973				Chassis No	VF73AHNYTJJ793471			
Contact No Mobile: 96676278				Engine No	10XTA41173070			
				Make/Model	CIT/GRAND C4 SPACETOURE 1.2 PURETECH 13			
				Colour/Trim	EBM LAZULI BLUE / 8LP TISSU MILAZZO G			
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	28/06/2021/ 12:36	BLC	442 / CocoLu	16670			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2500.00
RENEW BONNET, FRT BUMPER, FRT AIRDAM, FRT FENDER LH, FRT SUPPORT PANEL								
REPAIR FRT DOOR LH,								
E PNT88000								100.00
REMOVE & INSTALL FRT AIRDAM								
E PNT98000								3120.00
SPRAY PAINT FOR FRT AIRDAM, FRT FENDER LH, FRT BUMPER, BONNET								
FRT SUPPORT , FRT DOOR LH								
A 54900099								30.00
CHECL WIRING & ELECTRICAL SYSTEM								
A 10028901								225.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M	FRONT BUMPER				1.00	1031.00	0.00	1031.00
M	BUMPER BRACKET				1.00	330.00	0.00	330.00
M	BUMPER MOULDING				1.00	207.00	0.00	207.00
M	BUMPER MOULDING				1.00	227.00	0.00	227.00
M	BMPR RUBBR BOOT				1.00	276.00	0.00	276.00
M	GUARD GRILLE INFERIEUR				1.00	311.00	0.00	311.00
M	BADGE SUPPORT				1.00	205.00	0.00	205.00
M	CHEVRON EMBLEM SUPERIEUR				1.00	161.00	0.00	161.00
M	CHEVRON EMBLEM INFERIEUR				1.00	161.00	0.00	161.00
M	BRACKET SET				1.00	125.00	0.00	125.00
M	BUMPER MOULDING				1.00	173.00	0.00	173.00
M	BRACKET SET LAT				1.00	125.00	0.00	125.00
M	ABSORBERS SET				1.00	92.00	0.00	92.00
M	BUMPER BRACKET				1.00	516.00	0.00	516.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
GOH CHYAN YEE		Cust No/Name	/GOH CHYAN YEE
2 BISHAN STREET 25		Reg No/Reg Date	SJP5420K / 27/12/2018
#09-03		Date In/Mileage	/ 0
SINGAPORE 573973		Chassis No	VF73AHNYTJJ793471
Contact No Mobile: 96676278		Engine No	10XTA41173070
		Make/Model	CIT/GRAND C4 SPACETOURER 1.2 PURETECH 13
		Colour/Trim	EBM LAZULI BLUE / BLP TISSU MILAZZO G

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	28/06/2021/ 12:36	BLC	442 / CocoLu	16670

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	PLUG LH	1.00	96.00	0.00	96.00
M	FACE CROSSMEMBR SUP	1.00	226.00	0.00	226.00
M	AIR BULKHEAD LH	1.00	108.00	0.00	108.00
M	AIR BULKHEAD	1.00	154.00	0.00	154.00
M	BRACKET CROSSME LH ASS	1.00	196.00	0.00	196.00
M	FACING SUPPORT LH ASS	1.00	90.00	0.00	90.00
M	FRONT WING LH ASS	1.00	571.00	0.00	571.00
M	MUDGUARD LH ASS	1.00	194.00	0.00	194.00
M	ENGINE BONNET ASS	1.00	1042.00	0.00	1042.00
M	BONNET HINGE LH	1.00	178.00	0.00	178.00
M	FRONT LIGHT LH	1.00	409.00	0.00	409.00
M	HEADLIGHT ASSY LH	1.00	718.00	0.00	718.00
M	SPACETOURER 2018 - BODY KIT	1.00	1500.00	0.00	1500.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Parts	9,422.00
Labour	5,975.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	110.00
Total (w/o GST)	15,507.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.