



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|--|--------------------------------|------------|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | | | Ref: CS3/LPC21001726/T1qf3e2-1 | |
| | | | Date: 26/07/2021 | |
| | | | Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | YP 4870Z | Veh. Inspected | SLL 7636P |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | 20/21/21/VC00/024205 | Excess (\$) | 0.00 |
| | Assign From | GERALD POH | Assign Date | 28/06/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | HONDA VEZEL HYBRID | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2017 |
| | Chassis No. | RU31227752 | Colour | WHITE |
| | Odometer | 71916 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/60 R16 | TOURADOR | 6 mm |
| | L/H Front Tyre | 215/60 R16 | TOURADOR | 6 mm |
| | R/H Rear Tyre | 215/60 R16 | TOURADOR | 6 mm |
| | L/H Rear Tyre | 215/60 R16 | TOURADOR | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 03/02/2021 | Inspection Date | 09/02/2021 |
| | Survey held at | GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. | | |
| 5a. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | |