

FW: SKX 1014Y DOA : 25/06/21

Rasul (LKKAuto) <Rasul@lkkauto.com>

Wed 16/2/2022 5:22 PM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Hi Denise,

Case finalised

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Admin AP Automotive Services [mailto:mota@apautomotive.services]

Sent: Wednesday, 16 February, 2022 2:44 PM

To: Rasul (LKKAuto)

Cc: Juliana .; Marcus Teo; info; Paul Ho; ClickUp: SKX 1014Y

Subject: Re: SKX 1014Y DOA : 25/06/21

Dear Rasul

We are pleased to accept the finalised amount given as at \$3,500 with 5 days repair

Will forward LOD in a while

Best regards,

Juliana

AP Automotive Services Pte Ltd

ROC: 202022890H

BLK 9006 TAMPINES ST 93

#01-202 TAMPINES INDUSTRIAL PARK A

SINGAPORE 528840

TEL: 6970 4786 FAX: 6787 4886

On Thu, 3 Feb 2022 at 10:54, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Zaleha,

So sorry we unable to increase the amount.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Admin AP Automotive Services [mailto:mota@apautomotive.services]

Sent: Saturday, 29 January, 2022 9:29 AM

To: Rasul (LKKAuto)

Subject: Re: SKX 1014Y DOA : 25/06/21

Hi Rasul,

Can it close at \$3800?

Best regards,

Zaleha

AP Automotive Services Pte Ltd

ROC: 202022890H

BLK 9006 TAMPINES ST 93

#01-202 TAMPINES INDUSTRIAL PARK A

SINGAPORE 528840

TEL: 6970 4786 FAX: 6787 4886

On Thu, 27 Jan 2022 at 12:03, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Zaleha,

Can offer at 3500

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Admin AP Automotive Services [mailto:mota@apautomotive.services]

Sent: Wednesday, 26 January, 2022 3:12 PM

To: Rasul (LKKAUTO)
Subject: Re: SKX 1014Y DOA : 25/06/21

Hi Rasul,

Can we close at \$4,000.00 and 5 repair days?

Best regards,

Zaleha

AP Automotive Services Pte Ltd

ROC: 202022890H

BLK 9006 TAMPINES ST 93

#01-202 TAMPINES INDUSTRIAL PARK A

SINGAPORE 528840

TEL: 6970 4786 FAX: 6787 4886

On Mon, 17 Jan 2022 at 12:08, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Zaleha,

Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO)

Sent: Wednesday, 12 January, 2022 9:46 AM

To: Admin AP Automotive Services

Subject: SKX 1014Y DOA : 25/06/21

Hi Zaleha,

Kindly refer to attachment

We will be advising our Principal a cost of repair of LS \$3,350 /- with 5 days of lump sum repair, subject to their approval

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.