

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 3195P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WHEEL FENDER	CRACKED	121.00	121.00
1	HEADLAMP	CUT	480.00	480.00
1	HEADLAMP BRACKET	NOT NECESSARY	45.00	-
1	HEADLAMP COWLING	NOT NECESSARY	210.00	-
2	FRONT SIGNAL LAMP @\$78.00	O/S CUT	156.00	78.00
1	FRONT FORK ASSY	CRACKED	785.00	785.00
1	FRONT FORK UNDERBRACKET	BENT	195.00	195.00
2	FRONT WING MIRROR @\$65.00	CUT	130.00	130.00
2	FRONT FAIRING SIDE @\$185.00	N/S CUT	370.00	185.00
1	FRONT LH FOOTREST	BENT	65.00	65.00
2	BALANCER @\$35.00	NOT NECESSARY	70.00	-
2	HANDLE BAR @\$156.00	NOT NECESSARY	312.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	290.00	-
1	FRONT WHEEL SPINDLE	BENT	45.00	45.00
	LESS 10% DISCOUNT		-	-208.40
			3,274.00	1,875.60
	SPECIAL NETT ITEMS			
1	STEERING CONE AND BEARING (SN)	NECESSARY	90.00	90.00
1	FORK OIL (SN)	NECESSARY	40.00	40.00
1	FORK OIL SEAL (SN)	NECESSARY	30.00	30.00
1	SLIDER LH (SN)	CUT	80.00	70.00
1	REAR BOX (SN)	CUT	280.00	250.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			700.00	480.00
	<u>LABOUR</u>			
	LABOUR.		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00

Report Ref No. CS/LPC21007087/Aqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TOWING FEE.		40.00	40.00
			890.00	470.00
	GRAND TOTAL		4,864.00	2,825.60

RECOMMENDED COST OF LUMP SUM REPAIRS		2,250.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/LPC21007087/Aqf3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.