

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kembangan Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 44796691 (After Sales)
64796624 (Motorrad)

30/6/2021
Sunny only
10:30 am



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58794
Date Estimated : 26/06/2021
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Gudi Pandurang Mohan
130 Tanjong Rhu Road
#07-06

Singapore 436918

- ACCOUNT - 115

United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5963A	WBAXW120200R68159	23/06/2016	X4 xDrive20i	45508

DESCRIPTION

Replace front support panel ,front bumper include remove on attachment etc

Painting front bumper

To check electrical wiring system at the front section for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To supply front emboss number plate.

Sundries.

VALUE
1275 3,400.00
986 1,038.00
168 177.00
168 177.00
83.00
150.00

Total Labour 1: 5,025.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET	30	3.10	93.00
LH BRACKET	1	24.40	24.40
RH BRACKET	1	24.40	24.40
FLAP TOWING EYE	1	37.45	37.45
LH SIDE GRILLE CLOSED	1	114.00	114.00
FRT SHOCK ABSORBER ECE	1	63.05	63.05
LICENCE PLATE HOLDER ECE	1	69.90	69.90
SET COVER PRIMED (SRA)	1	78.65	78.65
FRT BUMPER CROSS MEMBER ECE	1	531.60	531.60
CLADDING BUMPER FRT (PDC/SCHWARZ)	1	318.90	318.90
FRT BUMPER PANEL PRIMED	1	1,326.25	1,326.25
UNDERRIDE GUARD PRIMED FRT (X-LINE)	1	308.35	308.35
AIR GUIDE MIDDLE FRT	1	39.70	39.70
CLIP	10	2.10	21.00
AIR DUCT	1	370.85	370.85
LH FOG LIGHT LED	1	455.50	455.50
ULTRASONIC SENSOR BLACK	4	251.20	1,004.80

