



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21007089/Etf3e2	
			Date: 12/08/2021	
			Code: UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SLD 5963A
	<b>Policy No.</b>	DHOM120043731901	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	M12D16052107	<b>Excess (\$)</b>	750.00
	<b>Assign From</b>	JOSEPHINE WONG	<b>Assign Date</b>	28/06/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	B.M.W. X4	<b>c.c</b>	1997
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	WBAXW120200R68159	<b>Colour</b>	BLACK
	<b>Odometer</b>	45652 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	245/50 R18	PIRELLI	5 mm
	<b>L/H Front Tyre</b>	245/50 R18	PIRELLI	5 mm
	<b>R/H Rear Tyre</b>	245/50 R18	PIRELLI	5 mm
	<b>L/H Rear Tyre</b>	245/50 R18	PIRELLI	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	25/06/2021	<b>Inspection Date</b>	30/06/2021
	<b>Survey held at</b>	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$120,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	