

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 58794**
Date Estimated : **26/06/2021**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Gudi Pandurang Mohan
130 Tanjong Rhu Road
#07-06

Singapore 436918

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5963A	WBAXW120200R68	23/06/2016	X4 xDrive20i	45508

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To Replace left headlight	457.00	0.00	457.00	✓
-----------------------------	--------	------	--------	---

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# BRACKET	33.20	1.00	0.00	33.20	✓ BR
# GRID LATERAL LH (X LINE)	90.95	1.00	0.00	90.95	✓ CUT
# CLASP PRIMED LH (X LINE)	83.40	1.00	0.00	83.40	✓ CUT
# ENGINE COMPARTMENT SHIELDING FRT	214.60	1.00	0.00	214.60	✓ BR
# EXPANDING RIVET BLACK	1.40	10.00	0.00	14.00	✓ nec
# LH BI XENON HEADLIGHT	2,449.90	1.00	0.00	2,449.90	✓ CUT

SUPPLEMENTARY ITEMS

Total Labour :	457.00
Total Parts :	2,886.05

3343.05