## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

28-Jun-21

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8900 U

ESTINIA	ATE REPAIR BILL FOR HYUNDAI IONIQ REGINIO. 311	0000			1
1 pc	Rear bumper du	912 1.16.		459.40	
1 pc	Rear bumper reinforcement .	7		294.80	
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$1	10.00		30.00	
1 pc	Rear bumper reinforcement centre lower bracket 7		\$	15.00	
1 pc	Lamp Assy- Rear fog 🗶			201.50	
	Rear bumper n/s & o/s stay @ \$138.10 -		\$ 2	276.20	
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10		\$	66.20	
2 pcs	Moulding Assy- Rear bumper center \$ 0.7		\$	216.50	
1 pc			\$	47.50	
1 pc	Rear licence lamp Assy		\$ 1	1,607.10	
		Less 20%	\$	321.42	
			\$ 1	1,285.68	
		( Kasw			
<u>S/N</u>		T. A	10/10	12	
 1 set	Rear bumper clips	Hp 2001	wo \$	48:00 30	
1 set	Reverse sensor 🗡	2 1-	\$ S	280.00	
	Rear number plate with casing	) N	\$	50.00 39	
1 pc	Total number plate that eachig	DIP	IIIa		
		C.('	Olen	50.00 🗶	
	Sundry	28/06/	218	55.00	
	To dismantle / replace reverse sensor to new bumper at reset to the same	and Rosen	\$	120.00 60	
	To dismantle / refit the inner garnishes, inner linings, inretrims, cushion seat, carpet, etc to facilitate repairs.	ner befor	s s	120.00 60 180.00 X	
	To dismantle, vaccuum, clean up on the tail gate lower glass. To fit up tail gate lower glass to the same	pa	\$	120.00	
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair,	t			_3,
	reshape and adjust of the end panel etc		\$	650.00 \$6	N
	To putty and spray painting on rear bumper, end panel ultants hence notify the following: the following:	l, Rear		650.00 30	
LKK Auto Consu	ultants hence notify pumper moulding center he following:	20	\$	600.00 \$	OV)
To resurvey before	re/after sprainting re/after sprainting ged part(s) during resurvey	nels.	\$		
To display damag	red part(s) during resurvey		\$	3,463.68	
	subject to confirmation				
<ul> <li>Third party survey</li> <li>No illegal modification</li> </ul>	ey is on a "Without Prejudice" basis cation(s) is allowed				
	tem(s) rys ber 역단환경 R COSTS ARE SUBJECTED TO G l approval from Insurance Company	ST)			

Acknowledged by Repair ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE Signature: ANY UNFORESEEN DAMAGES.

Date: