

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

28-Jun-21

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8900 U

1 pc	Rear bumper <i>de</i>	\$	459.40
1 pc	Rear bumper reinforcement <i>? fsu</i>	\$	294.80
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00 <i>? fsu</i>	\$	30.00
1 pc	Rear bumper reinforcement centre lower bracket <i>? fsu</i>	\$	15.00
1 pc	Lamp Assy- Rear fog <i>X su</i>	\$	201.50
2 pcs	Rear bumper n/s & o/s stay @ \$138.10 <i>? fsu</i>	\$	276.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10 <i>? fsu</i>	\$	66.20
1 pc	Moulding Assy- Rear bumper center <i>sur</i>	\$	216.50
1 pc	Rear licence lamp Assy <i>X su</i>	\$	47.50
		\$	1,607.10
		\$	321.42
		\$	1,285.68

540.72  
725.00  
1265.72

Less 20%

675.90  
20%  
540.72

### S/N

1 set	Rear bumper clips <i>su</i>
1 set	Reverse sensor <i>X su</i>
1 pc	Rear number plate with casing <i>su</i>

### Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To dismantle, vacuum, clean up on the tail gate lower glass. To fit up tail gate lower glass to the same

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc

<i>Rasu</i>	\$	48.00	30
<i>Hp 9000068</i>	\$	280.00	X
<i>3 days</i>	\$	50.00	35
<i>P/P</i>	\$	50.00	X su
<i>28/06/21</i>	\$	120.00	60
<i>Reey</i>	\$	180.00	X su
<i>before print</i>	\$	120.00	X su
	\$	650.00	300

To putty and spray painting on rear bumper, end panel, Rear bumper moulding center

To apply rustproofing on the repaired and replaced panels.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) not covered by the policy is subject to final approval from Insurance Company

ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

Acknowledged by Repairer: THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Signature:  
Date:

\$ 600.00 300  
\$ 80.00 X su  
\$ 3,463.68