

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Wednesday, 11 May 2022 10:30 AM
To: SUR; CS A Team
Subject: FW: REQUEST FINALISED FOR SFN 7575Y BMW 328I GT DOA 23.06.2021

From: Admin AP Automotive Services <mota@apautomotive.services>
Sent: Wednesday, 11 May 2022 10:29:44 am (UTC+08:00) Kuala Lumpur, Singapore
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Juliana . <juliana@apautomotive.services>; Paul Ho <paul@apautomotive.services>; Marcus Teo <marcus@apautosg.com>; Chrystia Liew <chrystia@apautomotive.services>; info <info@apautosg.com>; ClickUp: SFM 7575Y <a.c.1p1mx5a.u-37601221.b390559c-a80e-4f98-858f-5fd2aee8e6bf@tasks.clickup.com>
Subject: Re: REQUEST FINALISED FOR SFN 7575Y BMW 328I GT DOA 23.06.2021

Dear Rasul,

We accepted the offer of \$4,250.00 and 4 repair days.

We will submit the LOD accordingly.

Best regards,

Zaleha

AP Automotive Services Pte Ltd
ROC: 202022890H
BLK 9006 TAMPINES ST 93
#01-202 TAMPINES INDUSTRIAL PARK A
SINGAPORE 528840
TEL: 6970 4786 FAX: 6787 4886

On Tue, 10 May 2022 at 09:37, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Zaleha,

Refer to attachment

Audit checked part price is high, necessary adjustment required.

We will be advising our principal a cost of repair of L/S \$4,250.00 /- with 04 days of repair, subject to their approval

kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Admin AP Automotive Services <mota@apautomotive.services>
Sent: Wednesday, 4 May 2022 2:40 pm
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Juliana . <juliana@apautomotive.services>; Paul Ho <paul@apautomotive.services>; Marcus Teo <marcus@apautosg.com>; Chrystia Liew <chrystia@apautomotive.services>; info <info@apautosg.com>; ClickUp: SFM 7575Y <a.c.1p1mx5a.u-37601221.b390559c-a80e-4f98-858f-5fd2aee8e6bf@tasks.clickup.com>
Subject: Re: REQUEST FINALISED FOR SFN 7575Y BMW 328I GT DOA 23.06.2021

Hi Rasul,

Attached after repair photos as requested.

Kindly expedite the finalisation.

Best regards,

Zaleha

AP Automotive Services Pte Ltd

ROC: 202022890H

BLK 9006 TAMPINES ST 93

#01-202 TAMPINES INDUSTRIAL PARK A

SINGAPORE 528840

TEL: 6970 4786 FAX: 6787 4886

On Wed, 26 Jan 2022 at 09:55, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Zaleha,

Kindly email to me the resurvey after repair photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Admin AP Automotive Services [mailto:mota@apautomotive.services]
Sent: Tuesday, 25 January, 2022 3:30 PM
To: Rasul (LKKAuto)
Cc: Juliana .; Paul Ho; Marcus Teo; Chrystia Liew; info
Subject: REQUEST FINALISED FOR SFN 7575Y BMW 328I GT DOA 23.06.2021

Hi Sir / Madam

We seek your kind help if you could finalize the vehicle.

Looking forward to hear from you soon.

No	Vehicle Number	Make / Model	DOA	Estimate	Finalised	Surveyor
1	SFN 7575Y	BMW 328I GT	23.06.2021	\$31,010.93	\$6,900.00	RASUL

Please do not hesitate to contact me should you have any queries thereof.

Best regards,

Zaleha

AP Automotive Services Pte Ltd

ROC: 202022890H

BLK 9006 TAMPINES ST 93

#01-202 TAMPINES INDUSTRIAL PARK A

SINGAPORE 528840

